

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	OWL 20504 JV-P #005	Facility Type:	Tank Battery
Surface Owner:	Federal	Mineral Owner:	API No. 30-015-35435

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	18	26S	27E	2310'	South	2310'	East	East

Latitude 32.0414886 Longitude 104.2282181

NATURE OF RELEASE

Type of Release:	Oil & Produced Water	Volume of Release:	2bbls Oil & 18bbls Produced Water	Volume Recovered:	1bbls Oil & 17bbls Produced Water
Source of Release:	PLC Control Valve	Date and Hour of Occurrence:	10-17-2016 11:30 am	Date and Hour of Discovery:	10-17-2016 11:30 am
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour:				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
Describe Cause of Problem and Remedial Action Taken.*					
Facility operational control system (PLC) malfunctioned and failed to provide accurate operational data to alarms and system water stream control valve. Had the (PLC) repaired.					
Describe Area Affected and Cleanup Action Taken.*					
This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho will have the spill site inspected for any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature:	<i>Rebecca Haskell</i>				
Printed Name:	Rebecca Haskell				
Title:	Senior Environmental Coordinator				
E-mail Address:	rhaskell@concho.com				
Date:	November 18, 2016				
Phone:	432-683-7443				
OIL CONSERVATION DIVISION			Approved by Environmental Specialist:		
Approval Date:			Expiration Date:		
Conditions of Approval:			Attached <input type="checkbox"/>		

* Attach Additional Sheets If Necessary