

Received 3/9/2017

NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1630650258

OPERATOR

Initial Report X Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	COLT STATE COM #002H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:		API No.	30-015-40862
----------------	-------	----------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	05	25S	28E	200'	North	1000'	West	Eddy

Latitude 32.1660347 Longitude 104.1149368

NATURE OF RELEASE

Type of Release:	Produced Water	Volume of Release:	280bbls	Volume Recovered:	278bbls
Source of Release:	4" Suction Hose	Date and Hour of Occurrence:	10-11-2016 3:42 pm	Date and Hour of Discovery:	10-11-2016 3:42 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher – NMOCD / Amber Groves - SLO		
By Whom?	Robert Grubbs Jr	Date and Hour:	Wed 10/12/2016 8:50 AM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*



Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a 4" suction hose that failed. The bad section was of 4" hose was replace with a new hose.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within a lined facility. Vacuum trucks were dispatched to remove all freestanding fluids. Concho has had the free fluids and any impacted material inside the lined facility removed. The liner has been cleaned and the facility back in operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Robert Grubbs Jr.		Approved by Environmental Specialist: 	
Title: Senior HSE Coordinator		Approval Date: 3/20/17	Expiration Date: N/A
E-mail Address: <u>rgrubbs@concho.com</u>		Conditions of Approval: Containment cleaned & liner inspected	Attached <input type="checkbox"/>
Date: March 9, 2017 Phone: 432-683-7443			

* Attach Additional Sheets If Necessary

2RP-3973