

## Bratcher, Mike, EMNRD

---

**From:** Blaney, Karolina <Karolina.Blaney@wpxenergy.com>  
**Sent:** Monday, March 20, 2017 3:08 PM  
**To:** Weaver, Crystal, EMNRD; 'stucker@blm.gov'; Bratcher, Mike, EMNRD  
**Subject:** WPX RDU 33 - final C-141 report  
**Attachments:** RDU 33 - Final C-141.doc; RDU 33 Final C-141 Attachment.pdf

Good afternoon,  
Attached is the Final C-141 spill closure request.  
Please let me know if I need to make any revisions.  
Thank you and have a great afternoon,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Weaver, Crystal, EMNRD [mailto:Crystal.Weaver@state.nm.us]  
**Sent:** Tuesday, February 21, 2017 1:33 PM  
**To:** Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; 'stucker@blm.gov' <stucker@blm.gov>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>  
**Subject:** [EXTERNAL] RE: WPX RDU 33 - initial C-141 report

---

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

---

RE: WPX \* RDU #33 \* 30-015-040623 \* 2RP-4108

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4108.

Thank you,

**Crystal Weaver**  
Environmental Specialist  
OCD – Artesia District II  
811 S. 1<sup>st</sup> Street  
Artesia, NM 88210  
Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

---

**From:** Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]

**Sent:** Thursday, January 26, 2017 3:19 PM

**To:** 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>; Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Weaver, Crystal, EMNRD <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>

**Subject:** WPX RDU 33 - initial C-141 report

Good afternoon,

Attached is the initial C-141 for the RDU 33 produced water spill.

Thank you,

*Karolina Blaney*

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina

**Sent:** Friday, January 13, 2017 11:29 AM

**To:** 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>; 'Bratcher, Mike, EMNRD' <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; 'Weaver, Crystal, EMNRD' <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>

**Subject:** RE: WPX RDU 12 - initial spill notification

Good morning,

WPX had a spill yesterday, 1/12/17, at the RDU 33 tank battery; 30-015-40623 J-22-26S-30E. The spill was caused by human error. A valve on the unloading line was left open which resulted in a 100 bbl spill into lined SPCC containment. Unfortunately, the liner has a hole on the southeast corner and a small volume (less than 1 bbl) leaked out of the containment. I will submit the C-141 report within 15 days of the incident.

Thank you and have a great weekend,

*Karolina Blaney*

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina

**Sent:** Thursday, January 12, 2017 8:33 AM

**To:** 'stucker@blm.gov' <[stucker@blm.gov](mailto:stucker@blm.gov)>; 'Bratcher, Mike, EMNRD' <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; 'Weaver, Crystal, EMNRD' <[Crystal.Weaver@state.nm.us](mailto:Crystal.Weaver@state.nm.us)>

**Subject:** WPX RDU 12 - initial spill notification

Good morning,

WPX had a spill yesterday, 1/11/17, caused by human error; stuffing box failure. Approximately 12 bbls of oil and water was spilled with 4.5 bbls recovered from the pad. The spill migrated west of the pad, entered a dry drainage and migrated for about 100 yards. Due to access constraints, we were unable to vacuum the free standing oil from the drainage. To prevent from further migration, the oil was absorbed with dirt. The impacted area was GPS-ed and the end of the impacts in the drainage was additionally marked with a flag. We will start the excavation activities once I receive your approval. The line locate call was placed yesterday and we should be ready to go by Monday.

Please let me know if you would like an onsite prior to the excavation activities. We will do our best to minimize the impacts but, unfortunately, I think we will damage some vegetation during this cleanup.

Please let me know if you have any comments and suggestions.

Thank you for your help,

*Karolina Blaney*

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)