

Bratcher, Mike, EMNRD

From: Baker, Larry <Larry.Baker@apachecorp.com>
Sent: Tuesday, April 4, 2017 1:07 PM
To: Pair, Randal; Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Cc: David Adkins; Kimberly M. Wilson (kwilson@talonlpe.com)
Subject: RE: Loco Hills SWD Booster Station 2RP-3460
Attachments: Apache Corp - Loco Hills SWD Booster Station - 2RP-3460.pdf

All,

Attached are the laboratory analysis and site maps for the excavated areas. Mr. Pair I understand your concern around sample point 8 which currently is excavated to a depth of 4 feet and I propose that a 20 mil liner be installed prior to backfilling. The other sample point that has elevated chloride sample point 11 was a surface sample and will have that removed during backfilling activities and a confirmation sample collected for analysis prior to backfilling that area. Apache respectfully request approval so we can conclude this matter. Please let me know if you have any questions or wish to discuss. Thanks and have a good day.

Bruce Baker
Apache Corporation
Environmental Technician
Northwest District
Email: larry.baker@apachecorp.com
Mobile: 432-631-6982

From: Pair, Randal [mailto:rpair@blm.gov]
Sent: Wednesday, March 29, 2017 5:25 PM
To: Kimberly M. Wilson <kwilson@talonlpe.com>
Cc: Baker, Larry <Larry.Baker@apachecorp.com>; David Adkins <dadkins@talonlpe.com>
Subject: Re: Loco Hills SWD Booster Station

Sorry for teh dealy on this - I injured a knee over New years, had surgery in early January, was out for all of January, and have only worked part-time since then. This one just got lost in my email.

Remind me - did you have to notify OCD on this one? And if so, have they approved?

This report is light on on fdetails. But BLM generally does not allow chloride levels above 1,000 ppm within 4-feet of teh surface. Several of your samples exceed this. Are you proposing just to backfill with clean material? If so, I think you need to excavate a few more feet in those spots with high Chloride; then we can discuss further.

Randal "Randy" Pair
Envir. Protection Specialist - Realty Compliance
office: 575.234.6240
cell: 575.361.0062
email: rpair@blm.gov

On Mon, Jan 30, 2017 at 10:35 AM, Kimberly M. Wilson <kwilson@talonlpe.com> wrote:

Good morning Randy,

Have you had a chance to look-over the lab results from our site visit? Can we get permission to backfill and complete our remediation activities at the above referenced location?

I have attached the lab table along with the site maps for easy reference.

Thank you.

Kimberly M. Wilson

Project Manager

Office: 575.746.8768

Direct: 575.616.4023

Cell: 575.602.3826

Fax: 575.746.8905

Emergency: 866.742.0742

Web: www.talonlpe.com



From: Kimberly M. Wilson

Sent: Monday, January 09, 2017 1:21 PM

To: Pair, Randal

Cc: Baker, Larry; David Adkins

Subject: Loco Hills SWD Booster Station

Good afternoon Randy,

Attached please find the lab results from our December 2016 site visit along with the site map for the above referenced project.

On behalf of our client, we would respectfully request permission to complete backfilling operations on this project.

Respectfully submitted,

Kimberly

Kimberly M. Wilson

Project Manager

408 West Texas Avenue

Artesia, New Mexico 88210

(575) 746.8768 office

(575) 616.4023 direct

(575) 602.3826 cell

(866) 742.0742 emergency

Email: kwilson@talonlpe.com

Web: www.talonlpe.com

