

Bratcher, Mike, EMNRD

From: Tucker, Shelly <stucker@blm.gov>
Sent: Wednesday, April 19, 2017 3:39 PM
To: Blaney, Karolina
Cc: Bratcher, Mike, EMNRD; Weaver, Crystal, EMNRD
Subject: Re: WPX RDU 33 - final C-141 report

I am ok with you blending it and reusing that material.

If you have any questions or concerns, please do not hesitate to contact me.

Sincerely,

Shelly J Tucker

Environmental Protection Specialist
O&G Spill/Release Coordinator

Bureau of Land Management
620 E. Greene St
Carlsbad, NM 88220

575.234.5905 - Direct
575.361.0084 - Cellular
575.234.6235 - Emergency Spill Number

stucker@blm.gov

The **BLM acceptance/approval does not** relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment or if the location fails to reclaim properly. In such an event that the location does not revegetate, or future issues with contaminants are encountered, the operator will be asked to address the issues until the contaminant issues are fully mitigated and the location is successfully reclaimed. In addition, BLM approval does not relieve the operator of responsibility for compliance with any other federal, state or local laws/regulations.

Confidentiality Warning: This message along with any attachments are intended only for use of the individual or entity to which it is addressed and may contain information that is privileged or confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient or the employee or agent responsible for delivering this message to the intended recipient, you are hereby notified that any dissemination, distribution, or copying of this communication is strictly prohibited. If you have received this communication in error, please notify the sender immediately.

On Wed, Mar 22, 2017 at 8:57 AM, Blaney, Karolina <Karolina.Blaney@wpxenergy.com> wrote:

Hey Shelly,

Would blending with clean dirt and reusing for pad surface maintenance be OK with you?

Please let me know.

Thank you,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]

Sent: Wednesday, March 22, 2017 8:55 AM

To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>

Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>

Subject: [EXTERNAL] RE: WPX RDU 33 - final C-141 report

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

RE: 2RP-4108

Karolina,

In this instance, since it is a relatively small amount of material, OCD will approve your request, if BLM is OK with it as well. If so, I will approve your request for closure of 2RP-4108.

Thank you for your cooperation,

Mike Bratcher

NMOCD District 2

811 S. First St.

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

<end>

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]

Sent: Wednesday, March 22, 2017 8:48 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>

Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>

Subject: RE: WPX RDU 33 - final C-141 report

Good morning Mike,

I would like to request permission to blend the top 6" with clean soil and reuse at another location for surface maintenance. With your prior approval, the material would be used within the existing disturbance and will not affect vegetation.

Please let me know if this proposal is acceptable to OCD.

Thank you,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Bratcher, Mike, EMNRD [<mailto:mike.bratcher@state.nm.us>]
Sent: Wednesday, March 22, 2017 8:07 AM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; Weaver, Crystal, EMNRD
<Crystal.Weaver@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>
Subject: [EXTERNAL] RE: WPX RDU 33 - final C-141 report

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

RE: WPX * RDU 33 * 2RP-4108 * DOR: 1/2/17

Karolina,

OCD requests removal of material in the spill path, through the 6" interval. Once completed, let me know via email and this incident will be approved for closure.

If you have any questions or concerns, please contact me.

Thank you,

Mike Bratcher

NMOCD District 2

811 South First Street

Artesia NM 88210

575-748-1283 Ext 108

mike.bratcher@state.nm.us

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]

Sent: Monday, March 20, 2017 3:08 PM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>;
Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>

Subject: WPX RDU 33 - final C-141 report

Good afternoon,

Attached is the Final C-141 spill closure request.

Please let me know if I need to make any revisions.

Thank you and have a great afternoon,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Weaver, Crystal, EMNRD [<mailto:Crystal.Weaver@state.nm.us>]
Sent: Tuesday, February 21, 2017 1:33 PM
To: Blaney, Karolina <Karolina.Blaney@wpxenergy.com>; 'stucker@blm.gov' <stucker@blm.gov>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: [EXTERNAL] RE: WPX RDU 33 - initial C-141 report

CAUTION: This email was sent from an EXTERNAL source. Use caution when clicking links or opening attachments.

RE: WPX * RDU #33 * 30-015-040623 * 2RP-4108

Karolina,

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval. The OCD tracking number for this event is 2RP-4108.

Thank you,

Crystal Weaver

Environmental Specialist

OCD – Artesia District II

811 S. 1st Street

Artesia, NM 88210

Office: 575-748-1283 ext. 101

Cell: 575-840-5963

Fax: 575-748-9720

From: Blaney, Karolina [<mailto:Karolina.Blaney@wpxenergy.com>]

Sent: Thursday, January 26, 2017 3:19 PM

To: 'stucker@blm.gov' <stucker@blm.gov>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>

Subject: WPX RDU 33 - initial C-141 report

Good afternoon,

Attached is the initial C-141 for the RDU 33 produced water spill.

Thank you,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Friday, January 13, 2017 11:29 AM
To: 'stucker@blm.gov' <stucker@blm.gov>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>
Subject: RE: WPX RDU 12 - initial spill notification

Good morning,

WPX had a spill yesterday, 1/12/17, at the RDU 33 tank battery; 30-015-40623 J-22-26S-30E. The spill was caused by human error. A valve on the unloading line was left open which resulted in a 100 bbl spill into lined SPCC containment. Unfortunately, the liner has a hole on the southeast corner and a small volume (less than 1 bbl) leaked out of the containment. I will submit the C-141 report within 15 days of the incident.

Thank you and have a great weekend,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com

From: Blaney, Karolina
Sent: Thursday, January 12, 2017 8:33 AM
To: 'stucker@blm.gov' <stucker@blm.gov>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'Weaver, Crystal, EMNRD' <Crystal.Weaver@state.nm.us>
Subject: WPX RDU 12 - initial spill notification

Good morning,

WPX had a spill yesterday, 1/11/17, caused by human error; stuffing box failure. Approximately 12 bbls of oil and water was spilled with 4.5 bbls recovered from the pad. The spill migrated west of the pad, entered a dry drainage and migrated for about 100 yards. Due to access constraints, we were unable to vacuum the free

standing oil from the drainage. To prevent from further migration, the oil was absorbed with dirt. The impacted area was GPS-ed and the end of the impacts in the drainage was additionally marked with a flag. We will start the excavation activities once I receive your approval.

The line locate call was placed yesterday and we should be ready to go by Monday.

Please let me know if you would like an onsite prior to the excavation activities. We will do our best to minimize the impacts but, unfortunately, I think we will damage some vegetation during this cleanup.

Please let me know if you have any comments and suggestions.

Thank you for your help,

Karolina Blaney

Environmental Specialist

WPX Energy

Office: (575) 885-7514

Cell: (970) 589-0743

karolina.blaney@wpxenergy.com