

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report     Final Report

Name of Company - <i>Clayton Williams Energy, Inc.</i>	Contact - <i>Dave Dunlap</i>
Address - <i>6 Desta Drive, Ste 2100</i>	Telephone No. <i>575- 390-2062</i>
Facility Name - <i>Jenna Com</i>	Facility Type - <b>SWD Facility</b>
Surface Owner - <i>BLM</i>	Mineral Owner: <i>BLM</i>
Lease No. <i>25706</i>	

**LOCATION OF RELEASE**

Unit Letter <i>I</i>	Section <i>5</i>	Township <i>17S</i>	Range <i>29 E</i>	Feet from the <i>2110</i>	North/South Line <i>South</i>	Feet from the <i>990</i>	East/West Line <i>East</i>	County <i>Eddy Co.</i>
-------------------------	---------------------	------------------------	----------------------	------------------------------	----------------------------------	-----------------------------	-------------------------------	---------------------------

Latitude                      Longitude                      *API 30-015-29260*

**NATURE OF RELEASE**

Type of Release - <i>Produce Water</i>	Volume of Release - <i>80 Bbls</i>	Volume Recovered - <i>75 Bbls</i>
Source of Release- <i>SWD facility overflowed</i>	Date and Hour of Occurrence <i>7 - 19 - 13 @ Early morning</i>	Date and Hour of Discovery <i>7 - 19 - 13 @ ~ 0830 Hrs</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <i>BLM- Jim Amos</i>	
By Whom? <i>Dave Dunlap.... Production Field Foreman</i>	Date and Hour <i>7 - 19 - 13 @ ~ 0900 Hrs</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>Na</i>	

If a Watercourse was Impacted, Describe Fully. \* *Na*

Describe Cause of Problem and Remedial Action Taken.\* *The high fluid level automation system failed and allowed tanks to overflow water in to the fire wall (dikes) then on to the road near the battery. We have recovered all free fluids standing at present time which it consisted of ~ 40% rain water and produced water mixed. Also the automation system has been fixed. Delineation/Excavation process will be performed accordingly by BLM requirements once the soils affected become dry and up on meeting at the site with BLM reps.*

Describe Area Affected and cleanup Action Taken:

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
	Approved by District Supervisor:	
Printed Name: <i>Luis Gonzalez</i>	Approval Date:	Expiration Date:
Title: <i>Environmental Regulatory Administrator</i>	Conditions of Approval:	
E-mail Address: <i>lgonzalez@claytonwilliams.com</i>	Attached <input type="checkbox"/>	
Date: <i>July 22, 2013</i> Phone: <i>432-661-4708</i>		

\* Attach Additional Sheets If Necessary