

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

### Release Notification and Corrective Action

nAB1630550781

**OPERATOR**

Initial Report  Final Report

Name of Company	OXY USA INC	Contact	CASEY L SUMMERS
Address	PO BOX 4294; HOUSTON, TX 77210	Telephone No.	575-513-8289
Facility Name	GILA 12 FEDERAL #2H BATTERY	Facility Type	BATTERY
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-36401

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	24S	30E	630	SOUTH	2240	EAST	EDDY

Latitude N 32.22696 Longitude W 103.83256 NAD83

### NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	10 bbls oil. 40 bbls produced water	Volume Recovered	5 bbls
Source of Release	Failure of the emergency shut off valve	Date and Hour of Occurrence	10/21/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher. Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International, Inc.	Date and Hour	10/21/2016 2 3:33 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Failure of the emergency shut off valve caused the tank to spill over and leak 10 bbls of oil and 40 bbls of produced water. A vacuum truck recovered 5 bbls of fluids and the valve was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 300' x 80' both on and off location. Remediation was completed in accordance with the remediation plan approved for the release (2RP-3965) by Shelly Tucker of the BLM on 11/21/2016 and Mike Bratcher of the NMOCD on 11/29/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: CASEY L SUMMERS	Approved by Environmental Specialist: 		
Title: ENVIRONMENTAL ADVISOR	Approval Date: 9/26/17	Expiration Date: N/A	
E-mail Address: casey_summers@oxy.com	Conditions of Approval: Like approval BLM		Attached <input type="checkbox"/>
Date: 6-2-17 Phone: 575-513-8289			

\* Attach Additional Sheets If Necessary