

AMENDED COPY

Received 10/24/2017

NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1720628182

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Quick Draw 22 D #1 Battery	Facility Type: Producing Oil Well
Surface Owner: BLM	Mineral Owner:
API No. 30-015-37377	

LOCATION OF RELEASE

Unit Letter D	Section 22	Township 20S	Range 25E	Feet from the 330'	North/South Line North	Feet from the 330'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude __32.5651817__ Longitude __-104.480072__

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: estimated 15 bbls oil	Volume Recovered: 10 bbls oil
Source of Release: Tank Battery	Date and Hour of Occurrence 7-22-17 12:45 pm	Date and Hour of Discovery 7-22-17 12:45 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, NMOCD	
By Whom? Zack Thomas	Date and Hour 7-22-17 3:40 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Lightning struck tank battery causing fire. Well was shut-in and all separation equipment isolated. Atoka, La Huerta, and Riverside Fire Departments were dispatched to put out fire.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Lined secondary containment as well as a 10' x 40' area South of tanks off of the pad surface. Vacuum truck used to recover all standing fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Zack Thomas	Amended copy - Accepted for Record	
Title: Environmental Rep.	Approval Date:	Expiration Date:
E-mail Address: zthomas@mewbourne.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-24-17	Phone: 575-602-2188	

* Attach Additional Sheets If Necessary

2RP-4304