

Bratcher, Mike, EMNRD

From: Rory McMinn <rory@rmcminn.com>
Sent: Monday, January 22, 2018 9:12 AM
To: Bratcher, Mike, EMNRD
Cc: Weaver, Crystal, EMNRD; MNaranjo@slo.state.nm.us; Honea, Tammy
Subject: Re: Amended C-141 to include GPS and Final C-141

Thank you both for your email responses and instructions. I am trying to get a third party involved to perform the procedures as presented.

Rory McMinn
575/626-7100 Cell

On Jan 22, 2018, at 9:01 AM, Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> wrote:

RE: Quatro Osos * Frank P St 2 * 2RP-4548

Mr. McMinn,

For clarification, OCD entered the wrong coordinates on the C-141 you submitted for the above referenced release (It appears you did not list any coordinates when submitted). The correct coordinates for this well are: 33.4285316N 104.1912994W.

You do not need to do anything. I will correct the coordinates on a copy of the original submittal and place it in the file.

Please note that the proposed remedial effort mentioned on the C-141, may be an approved remedial method, however, OCD will require analytical data be obtained in a manner that provides vertical and horizontal definition of any contaminant impact. Once that data has been obtained, and a site ranking established per current OCD guidelines, any proposed remedial effort may then be evaluated. The current efforts may be considered "immediate response actions", but the incident will remain open in OCD database until analytical data has been provided. Please notify the OCD District 2 office at a minimum, 48 hours prior to obtaining samples, where the analytical data from samples obtained, will be submitted to OCD.

If you have any questions or concerns, please contact me. Thanks in advance for your cooperation in this matter.

Best regards,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

From: Rory McMinn [<mailto:rory@rmcminn.com>]
Sent: Saturday, January 20, 2018 6:28 AM
To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD

<mike.bratcher@state.nm.us>

Cc: MNaranjo@slo.state.nm.us; Honea, Tammy <thonea@slo.state.nm.us>

Subject: Re: Amended C-141 to include GPS and Final C-141

Crystal,

I have received the email. I am not prepared to discuss further until it is reviewed and discussed internally. Thank you for the follow-up email.

Regards,
Rory McMinn

On 1/19/2018 2:53 PM, Weaver, Crystal, EMNRD wrote:

RE: Quatro Osos * Frank P State #2 * 30-00562331 * 2RP-4548

Hello Rory,

As I mentioned to you when you stopped by our office the other day. I had added the coordinates to the original Initial C-141 once you provided them to me in the follow up email you sent me on 1/2/18. Immediately following the coordinate addition to the form, the form was then processed. Also I had explained to you when you came in to visit that OCD has a procedure/process that each reportable spill is required to go thru. This release would require that we go thru the process and require the proper remediation steps in order to render this case closable. So next step following this email would be for your company to look over the COA document that is scanned directly behind the processed Initial C-141 that I attached above and follow what it says. It says that the next step in the process is to produce a delineation of the spill which involves sampling in a way (the COA even kind of guides you on how to sample) so that laboratory data can be your provided proof that the spill went down however deep and spread out however far and then you would follow the delineation with a plan of action (work plan), if any contamination remains, on how your company intends to handle the clean-up of the spill.

Hiring a 3rd party environmental contractor is good to help with this process since a good majority of the contractors around here are keyed in on what our process involves and what we expect. As for the Final C-141 that you had submitted on 1/11/18 OCD will not be able to accept that until we get to that point in the process.

Also you will want to include the State Land Office in all submissions that you communicate with us on cause they will have their own required needs throughout the process since they are both the surface and mineral owner for this location.

So with that said...

I have included a scanned copy of the signed Initial C-141 Remediation Permit along with an attached Conditions of Approval (COA). The OCD tracking number for this event is 2RP-4548, please refer to this tracking number on any and all submissions sent in to the OCD. Please remit a site characterization plan (see COA document included in attachment) or advise OCD of plan of action by no later than 1/26/18.

Thank you,

Crystal Weaver
Environmental Specialist
OCD – Artesia District II
811 S. 1st Street
Artesia, NM 88210
Office: 575-748-1283 ext. 101
Cell: 575-840-5963
Fax: 575-748-9720

-----Original Message-----

From: Rory McMinn [<mailto:rory@rmcminn.com>]

Sent: Thursday, January 11, 2018 11:22 AM

To: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bratcher, Mike, EMNRD
<mike.bratcher@state.nm.us>

Subject: Amended C-141 to include GPS and Final C-141

Crystal and Mike,

Here is a Corrected/Amended C-141 which incorporates the GPS coordinates for the Frank P State #2 operated by Quatro Osos E&P, LLC in the Diablo SA Field. I have also attached a Final C-141 after the cleanup.

Regards,

Rory McMinn

--

PK

□

--
PK□