

From: [Bratcher, Mike, EMNRD](#)
To: "Chase Settle"
Cc: [Weaver, Crystal, EMNRD](#); [Bob Asher](#)
Subject: RE: Backfill Request Compromise SWD #1 2RP-4208
Date: Tuesday, January 23, 2018 7:27:00 AM

RE: **2RP-4208**

-
Chase,

Thanks for the update. Once that portion of the project has been completed, your request to install the liner and backfill is approved.

Thank you,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

-
-

From: Chase Settle [mailto:Chase_Settle@eogresources.com]
Sent: Monday, January 22, 2018 6:31 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; Bob Asher <Bob_Asher@eogresources.com>
Subject: Re: Backfill Request Compromise SWD #1 2RP-4208

Mike,

We are completing that tomorrow morning using shovels since there are also electrical lines in that area.

Chase

Sent from my iPhone

On Jan 22, 2018, at 4:56 PM, Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> wrote:

** External email. Use caution. **

RE: 2RP-4208

Chase,

Was the impacted soil removed from around the pipeline as requested by OneOK?

Thanks,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

From: Chase Settle [mailto:Chase_Settle@eogresources.com]
Sent: Thursday, January 18, 2018 9:31 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>
Cc: Bob Asher <Bob_Asher@eogresources.com>
Subject: Backfill Request Compromise SWD #1 2RP-4208

Mike/Crystal,

I'm submitting this request to backfill at the Compromise SWD #1. Attached you will find the site map and a summary table of the sidewall samples collected. The excavation depth is 4 feet and the contractor is preparing for liner installation once the backfill request is approved.

Thank you,

Chase Settle, M.S.
Rep Safety & Environmental II

EOG Resources
105 S. 4th Street
Artesia, NM 88210
575-748-4171 (Office)
575-703-6537 (Cell)
<image001.png>