

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating, LLC (OGRID# 229137)	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No.: 432-683-7443
Facility Name: Patron 23 Federal #004H	Facility Type: Flowline
Surface Owner: BLM	Mineral Owner: Federal
API No.: 30-015-42451	

LOCATION OF RELEASE

Unit Letter P	Section 14	Township 25S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
-------------------------	----------------------	------------------------	---------------------	---------------	------------------	---------------	----------------	-----------------------

Latitude: **32.1222382** Longitude: **-103.9487228** NAD83

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 200bbls	Volume Recovered: 0bbls
Source of Release: Flowline	Date and Hour of Occurrence: January 28, 2017 11:00am	Date and Hour of Discovery: January 28, 2017 11:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Ms. Weaver-NMOCD Ms. Tucker-BLM	
By Whom? Rebecca Haskell	Date and Hour: January 28, 2017 5:11pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was due to a rupture in a flowline. The damaged section of flowline was replaced.

Describe Area Affected and Cleanup Action Taken.*

The release impacted the pasture northeast of the Patron 23 Federal #004H location. The impacted area was evaluated and a remediation work plan was subsequently drafted and approved by NMOCD & BLM. The remediation was carried out in accordance with the approved work plan and stipulations agreed upon by NMOCD & BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Sheldon L. Hitchcock		Approved by Environmental Specialist:	
Title: HSE Coordinator	Approval Date:	Expiration Date:	
E-mail Address: slhitchcock@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12/7/2017	Phone: 575-746-2010		

* Attach Additional Sheets If Necessary