

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nAB1716441175

OPERATOR
☐ Initial Report ☒ Final Report

Name of Company	Plains Marketing, LP	Contact	Camille Bryant
Address	577 US Hwy. 385 N., Seminole, Texas 79360	Telephone No.	(575) 441-1099
Facility Name	Hackberry Hills Fed #4	Facility Type	Tank Battery

Surface Owner	BLM	Mineral Owner	BLM	Lease No.	
---------------	-----	---------------	-----	-----------	--

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
F	22	22S	26E					Eddy

Latitude N 32.37848° Longitude W 104.2834°

NATURE OF RELEASE



Type of Release	Crude Oil	Volume of Release	116 bbls	Volume Recovered	2 bbls
Source of Release	Tank	Date and Hour of Occurrence	05/10/2017 @ 07:45	Date and Hour of Discovery	05/10/2017 @ 07:45
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher		
By Whom?	Camille Bryant	Date and Hour	05/10/2017 @ 13:55		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.* Plains driver was attempting to remove a bull plug from the tank valve when he inadvertently removed one part of the two part valve which resulted in a release of crude oil.

Describe Area Affected and Cleanup Action Taken. The released crude oil impacted an area of approximately 8,900 square feet on the caliche pad, the released fluid flowed south off the pad impacting approximately 750 square feet of pasture land. The impacted area was excavated and soil samples were collected for laboratory analysis. Excavated soil was transported under manifest to an NMOCD permitted disposal and the Site was backfilled with locally purchased, non-impacted material. Please reference the Remediation and Closure Report dated January 2018 for additional details.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Camille Bryant		Approved by District Supervisor: 	
Title: Remediation Supervisor		Approval Date: 4/30/18	Expiration Date: N/A
E-mail Address: cjbryant@paalp.com		Like approval BLM	
Date: 1/24/18 Phone: (575) 441-1099		Conditions of Approval: FINAL	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-4247

2RP-4247