

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 5/22/2018
NMOCD Dist 2

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1811533585

OPERATOR

☐ Initial Report ☒ Final Report


Name of Company: COG Operating LLC (OGRID 229137)	Contact: Robert McNeill	
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-683-7443	
Facility Name: Stonewall 9 Fee #001H Battery	Facility Type: Tank Battery	
Surface Owner: Private	Mineral Owner: Private	API No. 30-015-40925

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	09	19S	26E	300	South	330	West	Eddy

Latitude 32.6687469 Longitude -104.3944321 NAD83

NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 0.25 bbl. – Oil 10 bbl. – Produced Water	Volume Recovered: 0.25 bbl. – Oil 10 bbl. – Produced Water
Source of Release: Corroded Fitting	Date and Hour of Occurrence: April 22, 2018 8:00am	Date and Hour of Discovery: April 22, 2018 8:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.*		
The release was due to the nipple on the water side of the tester corroding and developing a hole. Nipple has been replaced.		
Describe Area Affected and Cleanup Action Taken.*		
All of the fluid remained inside of the lined containment. A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: DeAnn Grant	Approved by Environmental Specialist 	
Title: HSE Administrative Assistant	Approval Date: 5/23/18	Expiration Date: N/A
E-mail Address: agrant@concho.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: May 22, 2018	Phone: 432-253-4513	FINAL

* Attach Additional Sheets If Necessary

2RP-4716