

Bratcher, Mike, EMNRD

From: Bratcher, Mike, EMNRD
Sent: Wednesday, June 27, 2018 10:51 AM
To: 'DeAnn Grant'; Tucker, Shelly
Cc: Weaver, Crystal, EMNRD; jamos@blm.gov; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; Robert McNeill; Pruett, Maria, EMNRD
Subject: RE: (Final C-141) Cabo Wabo 24 Federal #005H (30-015-42482) 05-26-2018

RE: COG * Cabo Wabo 24 Fed 5H * **2RP-4797** (assigned 6/7/18) * DOR: 5/26/18

All,

This request for closure of the above referenced release is approved. Federal sites will require like approval from BLM.

DeAnn: If you would, please recheck where you access the RP numbers. My records indicate the RP number for this release was assigned on 6/7/18. Just want to make sure we don't have an issue with documents and/or data entries going where they are supposed to.

Thank you,

Mike Bratcher
NMOCD District 2
811 South First Street
Artesia, NM 88210
575-748-1283 Ext 108

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, June 26, 2018 11:38 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>
Cc: Weaver, Crystal, EMNRD <Crystal.Weaver@state.nm.us>; jamos@blm.gov; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>; Robert McNeill <RMcNeill@concho.com>
Subject: (Final C-141) Cabo Wabo 24 Federal #005H (30-015-42482) 05-26-2018

Mr. Bratcher/Ms. Tucker,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative. No RP or incident number has been assigned as of June 26, 2018.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC#

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Further, any contract terms proposed or purportedly accepted in this email are not binding and are subject to management's final approval as memorialized in a separate written instrument, excluding electronic correspondence, executed by an authorized representative of COG Operating LLC or its affiliates.