

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

OCD Rec'd:08/10/18

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: XTO Energy OGRID:5380	Contact: Kyle Littrell	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331	
Facility Name: Sizzler Fed 2H	Facility Type: Exploration and Production	
Surface Owner: State	Mineral Owner: State	API No: 30-015-44280

### LOCATION OF RELEASE

Unit Letter O	Section 6	Township 25S	Range 29E	Feet from the 180	North/South Line South	Feet from the 1650	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.152557 Longitude -104.020787 NAD83

### NATURE OF RELEASE


Type of Release Fresh water and chemical (scale inhibitor, PAA, biocide)	Volume of Release 300 bbls fresh water, 2 gal chemical	Volume Recovered 300 bbls fresh water, 2 gal chemical
Source of Release Frac Tanks	Date and Hour of Occurrence 7/27/2018 time unknown	Date and Hour of Discovery 7/27/2018 2:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Maria Pruett (NMOCD), Ryan Mann (SLO), Shelly Tucker (BLM)	
By Whom? Jacob Foust	Date and Hour: 7/27/2018 10:26 am by email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Frac tanks overflowed during filling. Valves were closed and flow to tanks was stopped.

Describe Area Affected and Cleanup Action Taken.\*  
All fluid remained in impermeable lined containment, with no impact to the soil. An XTO SH&E coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. All free standing fluids were recovered from containment and equipment was power washed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth		Approved by Environmental Specialist: Maria Pruett	
Title: Environmental Coordinator		Approval Date: 08/10/18	Expiration Date: N/A
E-mail Address: Amy_Ruth@xtoenergy.com		Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/10/2018 Phone: 575-689-3380			2RP-4911

\* Attach Additional Sheets If Necessary  
A#: pMAP1822263220  
I#: nMAP1822263454