

Note: Impacted soil located beneath the lined secondary containment will be remediated at time of abandonment of the tank battery.

LEGEND:

- ▲ Sidewall Sample
- Impacted Soil
- Floor Sample




Figure 3
 Site Details & Confirmation
 Soil Sample Locations Map
 SRO STATE COM #064H
 COG Operating, LLC.
 Eddy County, NM

Scale: 1" = 66'	
CAD By: JH	Checked By: NG
November 30, 2017	
LAT. N 32.0576019 , Long. W 104.0815811	
SW 1/4 NW 1/4 SEC 10 T26S R28E	
TRC Proj. NO.: 279785	



2057 Commerce Drive
 Midland, Texas 79703
 432.520.7720