OCD Rec'd: 08/23/18

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised April 3, 2017

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report											
Name of Company OXY USA INC Contact WADE DITTRICH											
Address PO BOX 4294; HOUSTON, TX 77210 Telephone No. 575-390-2828											
Facility Name CEDAR CANYON 23 FEDERAL #33H Facility Type WELL											
Surface Owner BLM Mineral Owner						BLM API No. 30-015-44074					
LOCATION OF RELEASE											
Unit Letter	Section	Township	Range	Feet from the N	Vorth/S	South Line Feet from the East/West Line				County	
1	22	24E	29E	2344	SC	DUTH	1199	Е	AST	EDDY	
Latitude_ 32.2020942 _ Longitude 103.9676325 NAD83											
NATURE OF RELEASE											
Type of Release PRODUCED WATER						Volume of Release 12 bbls Volume Re PRODUCED WATER				ecovered 9 bbls	
Source of Release 1.5 inch poly line connected to chemical trailer failure						Date and Hour of Occurrence Date and Hour of Discovery 8/10/2017					
Was Immediate Notice Given? If YES, To Whom?											
Yes No Not Required MIKE BRATCHER-NMOCD; Maria Pruett-NMOCD; SHELLY TUCKER-BLM											
By Whom? WADE DITTRICH						Date and Hour 8-11-2017 @ 12:35 PM					
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse.					
If a Watercourse was Impacted, Describe Fully.*											
If a watercourse was impacted, Describe Pully.											
Describe Cause of Problem and Remedial Action Taken.*											
Spill caused by a 1.5-inch poly line connected to chemical trailer failure. The leak has been repaired and is back in service. NMOCD Approved Plan: 2RP-4342											
Describe Area Affected and Cleanup Action Taken.*											
The affected area of the spill is 10x25 FT, Leak did not leave the location-9 bbls inside cont3 outside (measurements are subject to change with GPS											
tracking). Remediation completed in accordance with a remediation plan approved by the NMOCD and the SLO. Approved Plan 2RP-4342											
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and											
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability											
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health											
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.											
_federal, state,	or local lay	vs and/or regu	lations.				OH COM	OFDX	ATTION	DIVIGION	
	10	1. /		/			OIL CON	SERV	ATION	<u>DIVISION</u>	
Signature:	Signature: Well Sulfer										
Printed Name: WADE DITTRICH						Approved by Environmental Specialist:					
						Annenyal Dat	e: 08/27/18		Expiration E	Date: N/A	
						· ·			priation L		
E-mail Addre	ss: wade	dittrich@ox	y,com			Conditions of Approval: Attached			Attached		
Date: 8/20	/2018		Pho	ne: 575-390-2828		Like App	Like Approval BLM				

^{*} Attach Additional Sheets If Necessary