

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCD Rec'd: 08/24/18

Form C-141
Revised April 3, 2017

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: XTO Energy OGRID: 5380	Contact: Kyle Littrell	
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331	
Facility Name: Ross Draw 3031 Federal 1H	Facility Type: Exploration and Production	
Surface Owner: Federal	Mineral Owner: Federal	API No: 30-015-44446

LOCATION OF RELEASE

Unit Letter E	Section 31	Township 26S	Range 30E	Feet from the 170	North/South Line South	Feet from the 380	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.002244 Longitude -103.923635 NAD83

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 200 bbl	Volume Recovered 200 bbl
Source of Release Frac tank	Date and Hour of Occurrence 8/12/2018, 9:00 PM	Date and Hour of Discovery 8/12/2018, 9:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher and Maria Pruett (NMOCD), Jim Amos and Shelly Tucker (BLM)	
By Whom? Amy Ruth	Date and Hour: 8/13/2018, 10:29 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

During frac operations, a leak developed in the manway cover of a frac tank, releasing fluid into impervious lined containment. Flow to tank was stopped and repairs were made.

Describe Area Affected and Cleanup Action Taken.*

All fluid remained in impermeable lined containment, with no impact to the soil. All free standing fluids were recovered from containment and equipment was power washed. An XTO SH&E coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 08/27/18	Expiration Date: N/A
E-mail Address: Kyle.littrell@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/24/2018 Phone: 432-221-7331	Like Approval BLM	

* Attach Additional Sheets If Necessary

FINAL 2RP-4950

A#: pMAP1823936118 I#: nMAP1823936240