

District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
 Energy Minerals and Natural
 Resources Department

Form C-141
 Revised August 24, 2018
 Submit to appropriate OCD District office

Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

Incident ID	NAB1828257616
District RP	2RP-4996
Facility ID	fAB1828256842
Application ID	pAB1828258265

Release Notification

Responsible Party

Responsible Party	Enterprise Field Services, LLC	OGRID	241602
Contact Name	Alena Miro	Contact Telephone	575-628-6802
Contact email	ammiro@eprod.com	Incident # (assigned by OCD)	
Contact mailing address	PO Box 4324, Houston, TX 77210		

Location of Release Source

Latitude N 32.461424 Longitude W -104.197206
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	B-13 Pipeline	Site Type	Pipeline ROW
Date Release Discovered	9/21/2018	API# (if applicable)	N/A

Unit Letter	Section	Township	Range	County
N	21	21S	27E	Eddy

Surface Owner: State Federal Tribal Private (Name: *Frankie L Lara Revoc Living Trust*)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 83.37 MCF	Volume Recovered (Mcf) 0 MCF
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release

Natural gas was released due to a pipeline leak.

Incident ID	NAB1828257616
District RP	2RP-4996
Facility ID	fAB1828256842
Application ID	pAB1828258265


Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: *Each of the following items must be included in the closure report.*

- A scaled site and sampling diagram as described in 19.15.29.11 NMAC Not Applicable
- Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)
- Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)
- Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jon E. Fields Title: Director, Field Environmental
Signature:  Date: 10/4/18
email: jefields@eprod.com Telephone: 713-381-6684

OCD Only

Received by:  Date: 10/09/2018

Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.

Closure Approved by:  Date: 10/9/18
Printed Name: MBratcher Title: A/OI

Facility : B-13

Date : 9/21/2018

Enter data in shaded fields to calculate gas volumes released due to leak and/or blowdown of system.

Footage of Pipe blowdown	8448
Initial line pressure	623
Diameter of Pipe (inches)	6
Volume of Gas Blown Down	83,37453

MSCF

Calculations:

Volume of Gas Blown Down (MSCF) = Volume at pipeline conditions (ft³)*(Gauge Pressure (psig)+Atmospheric Pressure 13.7 psi)*Standard Temperature (60F) / (1000 scf/mscf)*Standard Pressure (14.7psi)*Temperature(F)*Z Factor

Volume at pipeline conditions (scf) = Diameter/12 (ft)*Diameter/12 (ft)*PI/4*Length of pipe (ft)

**Reference: Gas Pipeline Hydraulics, Menson (2005) Pages 132-134. Assuming the Ideal Gas Law and Tpipeline = Tatm.

Cause/ Reason: Unknown

Corrective Action: Isolated and blew down

Name: David Sedillo

Cell Phone: 575-200-7981