From:	Lucas Middleton
To:	Pruett, Maria, EMNRD
Subject:	[EXT] Remediation and Closure Sampling Plan for the SST #3 Release (2RP-4843), Eddy
Date:	Friday, October 12, 2018 7:59:17 PM
Attachments:	image006.png
	image010.png
	SST-3figure 3.pdf
	Remediation and Closure Sampling Plan for the SST #3 Release (2RP-4843), Eddy 10-11-18.pdf

Ms. Pruett,

I am emailing you in regards to the phone conversation on 10/10/18. I added two extra sample locations to the figure as discussed. We will be collecting closure samples for sample locations for R1-R7 and P1-P4. These samples will be sent to a laboratory and tested for all the constrictions in Table 1 NMAC 19.15.29. Showed in Figure 3a

Lucas Middleton Staff GeoScientist

Corporate Registrations: AZ Engineering/Geology/Surveying Firm (14070), SD Surveying Firm (C-7436), TX Engineering Firm (8877), TX Geology Firm (50254), TX PST CAPM

(CS-0000051), TX Surveying Firm (10162200), WY Engineering/Surveying Firm (S-1704)



Souder, Miller & Associates Engineering ♦ Environmental ♦ Surveying 201 S. Halagueno Carlsbad, NM 88220 www.soudermiller.com (575) 499-9244 (mobile)



Notice of Confidentiality and Privileged Status: This electronic mail message, including all attachments, is for the sole use of the intended recipient(s) and may contain confidential and/or privileged information or otherwise may be protected from disclosure. Any unauthorized review, use, disclosure, distribution or actions which rely on the contents of this information is prohibited. If you are not the intended recipient, please contact the sender and delete the message and any attachment(s) from your system.

Statement on Viruses and Harmful Software: While the message and attachment(s) have been scanned with anti-virus software, SMA does not guarantee that this message or any attachment(s)

is free of computer viruses or other harmful software. SMA does not accept liability for any damages caused by any computer virus or other harmful software transmitted herewith.