

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	NAB1832358581
District RP	2RP-5053
Facility ID	
Application ID	pAB1832358200

Release Notification

Responsible Party

Responsible Party XTO Energy	OGRID 5380
Contact Name Kyle Littrell	Contact Telephone 432-221-7331
Contact email Kyle_Littrell@xtoenergy.com	Incident # (assigned by OCD) NAB1832358581
Contact mailing address 522 W. Mermod, Carlsbad, NM 88220	

Location of Release Source

Latitude 32.305001 Longitude -103.803765
(NAD 83 in decimal degrees to 5 decimal places)

Site Name James Ranch Unit #124H	Site Type Production Well
Date Release Discovered 10/26/2018	API# (if applicable) 30-015-38113

Unit Letter	Section	Township	Range	County
F	17	23S	31E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: BLM)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input checked="" type="checkbox"/> Crude Oil	Volume Released (bbls) 3.6	Volume Recovered (bbls) 3.2
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 41.3	Volume Recovered (bbls) 36.8
	Is the concentration of total dissolved solids (TDS) in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)

Cause of Release



Fluids were released from the well head due to a stuffing box packing failure. A vacuum truck recovered free standing fluids. The packing was replaced and the well was returned to production.

Incident ID	NAB1832358581
District RP	2RP-5053
Facility ID	
Application ID	pAB1832358200

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? An unauthorized release of a volume of 25 barrels or more
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Notice provided by Amy Ruth to Maria Pruett, Mike Bratcher, and Jim Griswold (NMOCD), Shelly Tucker and Jim Amos (BLM), on 10/27/2018 by email	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: 	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Kyle Littrell</u> Signature:  email: <u>Kyle.Littrell@xtoenergy.com</u>	Title: <u>SH&E Coordinator</u> Date: <u>11-9-18</u> Telephone: <u>432-221-7331</u>
OCD Only Received by:  Date: <u>11/19/2018</u>	

Incident ID	NAB1832358581
District RP	2RP-5053
Facility ID	
Application ID	pAB1832358200

Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	>100 _____ (ft bgs)
Did this release impact groundwater or surface water?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within 300 feet of a wetland?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying a subsurface mine?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release overlying an unstable area such as karst geology?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Are the lateral extents of the release within a 100-year floodplain?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Did the release impact areas not on an exploration, development, production, or storage site?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.



Characterization Report Checklist: *Each of the following items must be included in the report.*

- ☐ Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.
- ☐ Field data
- ☐ Data table of soil contaminant concentration data
- ☐ Depth to water determination
- ☐ Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release
- ☐ Boring or excavation logs
- ☐ Photographs including date and GIS information
- ☐ Topographic/Aerial maps
- ☐ Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Incident ID	NAB1832358581
District RP	2RP-5053
Facility ID	
Application ID	pAB1832358200

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Kyle LittrellTitle: SH&E CoordinatorSignature: Date: 11-9-18email: Kyle_Littrell@xtoenergy.comTelephone: 432-221-7331**OCD Only**Received by: Date: 11/19/2018

Location:	JRU 124 (30-015-38113) pasture	
Spill Date:	10/26/2018	
Length of Spill=	35.00	feet
Width of Spill=	10.00	feet
Saturation (or depth) of Spill=	5.00	inches
Approximate Oil %	8	
Porosity Factor=	0.15	
Volume Recovered=	40.00	bbls

VOLUME OF LEAK		
Total Oil=	3.5	barrels
Total Produced Water=	40.4	barrels

VOLUME RECOVERED		
Total Oil=	3.2	barrels
Total Produced Water=	36.8	barrels

Location:	JRU 124 (30-015-38113) well pad	
Spill Date:	10/26/2018	
Length of Spill=	85.00	feet
Width of Spill=	25.00	feet
Saturation (or depth) of Spill=	1.00	inches
Approximate Oil %	8	
Porosity Factor=	0.03	
Volume Recovered=	-	bbls

VOLUME OF LEAK		
Total Oil=	0.1	barrels
Total Produced Water=	0.9	barrels

VOLUME RECOVERED		
Total Oil=	-	barrels
Total Produced Water=	-	barrels

From: [Pruett, Maria, EMNRD](#)
To: [Bustamante, Amalia, EMNRD](#)
Subject: FW: Release Notification - JRU #124 (API 30-015-38113)
Date: Tuesday, November 13, 2018 7:41:26 PM
Attachments: [image002.png](#)

From: Ruth, Amy <Amy_Ruth@xtoenergy.com>
Sent: Saturday, October 27, 2018 3:35 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Pruett, Maria, EMNRD <Maria.Pruett@state.nm.us>; Tucker, Shelly <stucker@blm.gov>; James Amos <jamos@blm.gov>
Cc: Griswold, Jim, EMNRD <Jim.Griswold@state.nm.us>; McSpadden, Wes <Wes_McSpadden@xtoenergy.com>; Sanders, Toady <Toady_Sanders@xtoenergy.com>; Littrell, Kyle <Kyle_Littrell@xtoenergy.com>; Foust, Bryan <Bryan_Foust@xtoenergy.com>
Subject: [EXT] Release Notification - JRU #124 (API 30-015-38113)

Good Afternoon,

This is sent as notification of a release of an amount greater than 25 barrels at the referenced facility that occurred yesterday. Details will be provided with an initial C-141. Please call with any questions or concerns. Thank you.

Release coordinates:

32.305065
-103.803886

Respectfully,

Amy C. Ruth

Delaware Basin Division

Environmental Coordinator

3104 E. Greene Street | Carlsbad, NM 88220 | M: 432.661.0571 | O: 575.689.3380



This document may contain information that is privileged, confidential and exempt from disclosure under applicable law. If you are not the intended recipient, you are notified that any unauthorized disclosure, copying, distribution or action on/of the contents of this document is prohibited.