

## Venegas, Victoria, EMNRD

---

**From:** DeAnn Grant <agrant@concho.com>  
**Sent:** Friday, February 1, 2019 8:42 AM  
**To:** Bratcher, Mike, EMNRD; jamos@blm.gov  
**Cc:** Griswold, Jim, EMNRD; Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Tucker, Shelly; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Sheldon Hitchcock; Dakota Neel; Robert McNeill; Rebecca Haskell; DeAnn Grant  
**Subject:** [EXT] (C-141 Final) Canvasback 13 Federal #001H Battery (30-015-39191) 01-05-2019 (2RP-5188)  
**Attachments:** (C-141 Final) Canvasback 13 Federal #001H Battery (30-015-39191) 01-05-2019 (2RP-5188).pdf

Mr. Bratcher/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

*DeAnn Grant*

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

