District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Responsible Party Vanguard Operating, LLC

Contact Name Jason Fisher

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1905638272
District RP	2RP-5258
Facility ID	fAB1833254645
Application ID	pAB1905634056

Release Notification

Responsible Party

OGRID 258350

Contact Telephone 505-918-0523

Contact email	l jfisher@v	nrenergy.com	-	Iı	Incident # (assigned by OCD) NAB1905638272		
Contact maili 79762	ng address	4001 Penbrook S	uite 201 Odessa,	, TX			
			Locatio	n of Rel	ase Source		
atitude 32.78	39546		(NAD 83 in	Lo. decimal degree	gitude -104.19898; to 5 decimal places)	5	
Site Name No	rthwest Sta	te Battery		Si	Site Type Tank Battery		
Date Release I	Discovered	1-21-2019		A	API# Please see attached		
Unit Letter	Section	Township	Range		County		
K	32	17S	28E	Eddy			
			Volume Re	covered (bbls) 0			
		Is the concentration of dissolved chloride			he Yes No	0	
Condensate	B	produced water >10,000 mg/l? Volume Released (bbls)			Volume Re	Volume Recovered (bbls)	
🛚 Natural Ga	S	Volume Released (Mcf) 436			Volume Re	Volume Recovered (Mcf) 0	
Other (desc	cribe)	Volume/Weight Released (provide units		ide units)	Volume/We	eight Recovered (provide units)	
The gas purchato flare.	aser reques	ted a reduction in	gas to make repa	airs in their I	Ialjamar plant. The r	repairs took 24 hours and the gas was sen	

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAB1905638272
District RP	2RP-5258
Facility ID	fAB1833254645
Application ID	pAB1905634056

Was this a major	If YES, for what reason(s) does the response	onsible party consider this a major release?		
release as defined by 19.15.29.7(A) NMAC?				
19.13.29.7(A) NIVIAC?				
Yes 🛛 No				
If YES, was immediate no	otice given to the OCD? By whom? To w	whom? When and by what means (phone, email, etc)?		
		, ,		
	T • T T			
	Initial k	Response		
The responsible p	party must undertake the following actions immediat	ely unless they could create a safety hazard that would result in injury		
☐ The source of the rele	ase has been stopped.			
☐ The impacted area has	s been secured to protect human health and	I the environment.		
Released materials ha	ve been contained via the use of berms or	dikes, absorbent pads, or other containment devices.		
☐ All free liquids and re	coverable materials have been removed as	nd managed appropriately.		
	l above have <u>not</u> been undertaken, explain			
	<u> </u>			
Dec 10 15 20 9 D (4) 3D4	A.Cl. 1			
has begun, please attach a	AC the responsible party may commence in partially of actions to date. If remedial	remediation immediately after discovery of a release. If remediation		
has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.				
I hereby certify that the infor-	mation given above is true and complete to the	best of my knowledge and understand that pursuant to OCD rules and		
regulations all operators are r	equired to report and/or file certain release not	ifications and perform corrective actions for releases which may endanger		
public health or the environm	nent. The acceptance of a C-141 report by the ate and remediate contamination that nose a thr	OCD does not relieve the operator of liability should their operations have eat to groundwater, surface water, human health or the environment. In		
addition, OCD acceptance of	a C-141 report does not relieve the operator of	f responsibility for compliance with any other federal, state, or local laws		
and/or regulations.				
Printed Name:Chuck	z Johnston	Title:EHS Operations Specialist		
	111			
Signature:	19M	Date:1-31-2019_		
email:cjohnston@vn	renergy.com	Telephone:432-202-4771		
OCD Only				
	9-15			
Received by:	ila Intamente	Date: 2/25/2019		

Form C-141 Page 6

State of New Mexico Oil Conservation Division

Incident ID	NAB1905638272	
District RP	2RP-5258	
Facility ID	fAB1833254645	
Application ID	pAB1905634056	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items	nust be included in the closure report.
☐ A scaled site and sampling diagram as described in 19.15.29.11 NM	IAC N/A
Photographs of the remediated site prior to backfill or photos of the must be notified 2 days prior to liner inspection)	e liner integrity if applicable (Note: appropriate OCD District office
☐ Laboratory analyses of final sampling (Note: appropriate ODC Dist	rict office must be notified 2 days prior to final sampling)
Description of remediation activities	
Signature: Date	se notifications and perform corrective actions for releases which 41 report by the OCD does not relieve the operator of liability e contamination that pose a threat to groundwater, surface water, 11 report does not relieve the operator of responsibility for The responsible party acknowledges they must substantially as that existed prior to the release or their final land use in
Received by:	Date: 2/25/2019
Closure approval by the OCD does not relieve the responsible party of liab remediate contamination that poses a threat to groundwater, surface water, party of compliance with any other federal, state, or local laws and/or regu	human health, or the environment nor does not relieve the responsible
Closure Approved by: Mala Jotamente	Date: 2/25/2019
Printed Name: Amalia Bustamante	Title: B.O.S O

<u>API</u>	<u>Well Name</u>	Well Number
30-015-10079	NORTHWEST ARTESIA UNIT	#001
30-015-10537	NORTHWEST ARTESIA UNIT	#004
30-015-02312	NORTHWEST ARTESIA UNIT	#005
30-015-01672	NORTHWEST ARTESIA UNIT	#007
30-015-10833	NORTHWEST ARTESIA UNIT	#010
30-015-20042	NORTHWEST ARTESIA UNIT	#011
30-015-01665	NORTHWEST ARTESIA UNIT	#014
30-015-20019	NORTHWEST ARTESIA UNIT	#016
30-015-30609	NW STATE	#001
30-015-30683	NW STATE	#002
30-015-30684	NW STATE	#003
30-015-30734	NW STATE	#004
30-015-30777	NW STATE	#006
30-015-30685	NW STATE	#007
30-015-30849	NW STATE	#009
30-015-30760	NW STATE	#010
30-015-30783	NW STATE	#011
30-015-30784	NW STATE	#012
30-015-30824	NW STATE	#014
30-015-30785	NW STATE	#015
30-015-30890	NW STATE	#016
30-015-31933	NW STATE	#017
30-015-31934	NW STATE	#018
30-015-30891	NW STATE	#019
30-015-30892	NW STATE	#020
30-015-30893	NW STATE	#028
30-015-36554	NW STATE	#029
30-015-36989	NW STATE	#030
30-015-37057	NW STATE	#031
30-015-37058	NW STATE	#032
30-015-28863	NW STATE	#033