

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

| | |
|----------------|---------------|
| Incident ID | NAB1905943420 |
| District RP | 2RP-5271 |
| Facility ID | |
| Application ID | pAB1905942994 |

Release Notification

Responsible Party

| | |
|--|--|
| Responsible Party: BTA Oil Producers, LLC | OGRID: 260297 |
| Contact Name: Bob Hall | Contact Telephone: 432-682-3753 |
| Contact email: bhall@btaoil.com | Incident # (assigned by OCD) NAB1905943420 |
| Contact mailing address: 104 S. Pecos St., Midland, TX 79701 | |

Location of Release Source

Latitude: 32.28212° Longitude: -104.10629°

(NAD 83 in decimal degrees to 5 decimal places)

| | |
|--|--|
| Site Name: Ogden 20509 1-3H Tank Battery | Site Type: Tank Battery |
| Date Release Discovered: 2/7/2019 | API# (if applicable) Nearest well: Ogden 20509 29 32 #1H API #30-015-44749 |

| Unit Letter | Section | Township | Range | County |
|-------------|---------|----------|-------|--------|
| B | 29 | 23S | 28E | Eddy |

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: BF&G Farms, LLC, PQB 1275, Loving, NM 88256)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

| | | |
|---|--|--|
| <input checked="" type="checkbox"/> Crude Oil | Volume Released (bbls) 10 BBL | Volume Recovered (bbls) 6 BBL |
| <input type="checkbox"/> Produced Water | Volume Released (bbls) | Volume Recovered (bbls) |
| | Is the concentration of dissolved chloride in the produced water >10,000 mg/l? | <input type="checkbox"/> Yes <input type="checkbox"/> No |
| <input type="checkbox"/> Condensate | Volume Released (bbls) | Volume Recovered (bbls) |
| <input type="checkbox"/> Natural Gas | Volume Released (Mcf) | Volume Recovered (Mcf) |
| <input type="checkbox"/> Other (describe) | Volume/Weight Released (provide units) | Volume/Weight Recovered (provide units) |

Cause of Release

A spray of oil from a heater released oil into the lined secondary containment and onto land adjacent to the Ogden 1-3H Tank Battery.



State of New Mexico
Oil Conservation Division

| | |
|----------------|---------------|
| Incident ID | NAB1905943420 |
| District RP | 2RP-5271 |
| Facility ID | |
| Application ID | pAB1905942994 |

| | |
|---|--|
| Was this a major release as defined by 19.15.29.7(A) NMAC? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, for what reason(s) does the responsible party consider this a major release? |
| If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? | |

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

| |
|--|
| <input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately. |
| If all the actions described above have <u>not</u> been undertaken, explain why: <u>Additional Information:</u> Immediate Action was taken to recover crude oil from the lined secondary containment and from the surface of the adjacent farm land. Impacted soil has been removed and closure samples have taken to show that remediation has been completed. Full details will be provided in report to request closure. |
| Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation. |
| I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. |
| Printed Name: Bob Hall Title: Environmental Manager Signature:  Date: 2/20/2018 email: bhall@btaoil.com Telephone: 432-682-3753 |
| <u>OCD Only</u> Received by:  Date: 2/28/2019 |