Bratcher, Mike, EMNRD

From: Hamlet, Robert, EMNRD

Sent: Thursday, December 27, 2018 8:58 AM

To: DeAnn Grant

Cc: Bratcher, Mike, EMNRD; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca

Haskell

Subject: RE: (C-141 Initial) Crapshoot 13 Federal #001H (30-015-42323) 12-08-2018

DeAnn,

The OCD tracking number for this release event is **2RP-5134**.

Thank you

From: Bustamante, Amalia, EMNRD

Sent: Thursday, December 27, 2018 8:39 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us> **Cc:** Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>

Subject: RE: (C-141 Initial) Crapshoot 13 Federal #001H (30-015-42323) 12-08-2018

2RP-5134 paperwork in L: drive

Amalia Bustamante

Oil Conservation Division-District II

From: Bratcher, Mike, EMNRD < mike.bratcher@state.nm.us>

Sent: Friday, December 21, 2018 9:11 AM

To: Bustamante, Amalia, EMNRD < Amalia. Bustamante@state.nm.us>

Cc: Hamlet, Robert, EMNRD < Robert. Hamlet@state.nm.us>

Subject: FW: (C-141 Initial) Crapshoot 13 Federal #001H (30-015-42323) 12-08-2018

From: DeAnn Grant <a grant@concho.com > Sent: Friday, December 21, 2018 8:46 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Tucker, Shelly <stucker@blm.gov>

Cc: jamos@blm.gov; Griswold, Jim, EMNRD < Jim.Griswold@state.nm.us>; Ike Tavarez < itavarez@concho.com>; Robert

McNeill < RMcNeill@concho.com>; Sheldon Hitchcock < SLHitchcock@concho.com>; Dakota Neel

<<u>DNeel2@concho.com</u>>; Rebecca Haskell <<u>RHaskell@concho.com</u>>; DeAnn Grant <<u>agrant@concho.com</u>>

Subject: [EXT] (C-141 Initial) Crapshoot 13 Federal #001H (30-015-42323) 12-08-2018

Mr. Bratcher/Ms. Tucker,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered

amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant agrant@concho.com

COG Operating LLC#

600 W Illinois Avenue | Midland, TX 79701 Direct: 432-253-4513 | Main: 432.683.7443

