

Location:	JRU DI1A #203H (30-015-43237)	
Spill Date:	4/21/2019	
Length of Spill=	15.00	feet
Width of Spill=	9.00	feet
Saturation (or depth) of Spill=	2.00	inches
Approximate Oil %	-	
Porosity Factor=	0.03	
Volume Recovered=	-	bbls

VOLUME OF LEAK		
Total Oil=	-	barrels
Total Produced Water=	0.12	barrels