

Location:	Avalon Delaware Unit #562 (30-015-24377)	
Spill Date:	5/1/2019	
Approximate Area=	128	ft ²
Average Saturation (or depth) of Spill=	6.25	inches

Approximate Oil %	-	
Average Porosity Factor=	0.15	
Approximate Volume Recovered=	7.1	bbls

VOLUME OF LEAK		
Total Oil=	0.0	barrels
Total Produced Water=	8.9	barrels

VOLUME RECOVERED		
Total Oil=	0.0	barrels
Total Produced Water=	7.1	barrels