District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Incident ID	
District RP	
Facility ID	
Application ID	

Release Notification

Responsible Party

Responsible Party	Enterprise Field Services, LLC	OGRID	241602
Contact Name	Alena Miro	Contact Telephone	575-628-6802
Contact email	ammiro@eprod.com	Incident # (assigned by (DCD)
Contact mailing add	ress PO Box 4324, Houston, TX 77210		

Location of Release Source

Latitude	N32.061543	Longi

_____Longitude _____W -104.172813 (NAD 83 in decimal degrees to 5 decimal places)

Site Name CGP1 Location	Site Type Pipeline ROW
Date Release Discovered 5/22/2019	API# (if applicable) N/A

Unit Letter	Section	Township	Range	County
А	10	26S	27E	Eddy

Surface Owner: State Federal Tribal Private : N/A

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Condensate	Volume Released (bbls)	Volume Recovered (bbls)
🛛 Natural Gas	Volume Released (Mcf) 3.05 MMCF	Volume Recovered (Mcf) 0 MCF
Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
C CD 1		

Cause of Release

Approximately 3.05 MMscf of gas was release due to a controlled blowdown of the pipeline to facilitate repair of a pipeline isolation valve.

Form C-141

Page 2

State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?		
release as defined by	The release is considered a major release as the estimated volume of gas released exceeded the major release		
19.15.29.7(A) NMAC?	thresholds as defined in 19.15.29.7(A).		
🛛 Yes 🗋 No			
	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?		
Yes; Jim Griswold and Mike F	Bratcher were notified via email of all information contained in the initial notification C-141 form on 5/22/2019		
at 1:55 pm	Matcher word normal of an information contained in the initial normation C-141 form on 5/22/2019		
	Initial Response		
The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury			
The source of the release has been stopped.			
The impacted area has been secured to protect human health and the environment.			
Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.			
All free liquids and recoverable materials have been removed and managed appropriately.			

If all the actions described above have not been undertaken, explain why:

N/A

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Jon E. Fields	Title: Director, Field Environmental
Signature: Kuly	Date: <u>6-5-19</u>
email:	Telephone: 713-381-6684
OCD Only	
Received by:	Date:

Form C-141 Page 6 State of New Mexico Oil Conservation Division

Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Jon E. Fields	Title: Director, Field Environmental	
Signature:	Date:6-5-19	
email: jefields@eprod.com	Telephone: 713-381-6684	
OCD Only		
Received by:	Date:	
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.		
Closure Approved by:	Date:	
Printed Name:	Title:	