

Location:	JRU SWD riser 105 (30-015-43607 JRU DI1 161H)	
Spill Date:	7/13/2019	
Approximate Area=	1,002.00	ft ²
Average Saturation (or depth) of Spill=	4.50	inches

Approximate Oil %	-	
Average Porosity Factor=	0.20	
Approximate Volume Recovered=	0	bbls

VOLUME OF LEAK		
Total Produced Water=	13.38	barrels