Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD Sent: Thursday, June 13, 2019 9:59 AM

To: 'Karrigan, Callie N. (MRO)'; Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD

Cc: Castro, Isaac (MRO); Heather Patterson

Subject: RE: Marathon Oil Company - Initial C141 - Cypress 1H

RE: Marathon Oil Company - Initial C141 - Cypress 1H

All,

The OCD tracking number for this release event is 2RP-5480. Thank you,

Victoria Venegas **EMNRD** OCD-District II 811 S First St. Artesia NM 88210 Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Karrigan, Callie N. (MRO) < cnkarrigan@marathonoil.com>

Sent: Tuesday, June 11, 2019 2:15 PM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>;

Hamlet, Robert, EMNRD < Robert. Hamlet@state.nm.us>

Cc: Castro, Isaac (MRO) <icastro@marathonoil.com>; Heather Patterson <heather.patterson@soudermiller.com>

Subject: [EXT] Marathon Oil Company - Initial C141 - Cypress 1H

Good afternoon,

Please see the attached initial C141.

Thank you,

Callie

From: Karrigan, Callie N. (MRO) Sent: Friday, June 7, 2019 9:27 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>;

Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; jim.griswold@state.nm.us

Cc: Castro, Isaac (MRO) <icastro@marathonoil.com>; Heather Patterson <heather.patterson@soudermiller.com>

Subject: Marathon Oil Company - 24 hour notification - Cypress 1H

Good morning,

Last night at 6:30 pm, a third party working near the Cypress 1H location reported a load line leak. Upon further investigation by the Operator, the water load out valve at the load out pot was left cracked. Approximately 103 bbls of produced water was released. Approximately 60 bbls of standing fluids were recovered via vac truck.

A C141 will be submitted shortly.

Thank you,

Callie Karrigan
HES Professional – Environmental
Office: 575-297-0956

Cell: 405-202-1028