

Hamlet, Robert, EMNRD

From: Hamlet, Robert, EMNRD
Sent: Wednesday, August 14, 2019 10:20 AM
To: 'Castro, Isaac (MRO)'
Cc: Heather Patterson; Venegas, Victoria, EMNRD; Johnson, Misti M. (MRO); Bratcher, Mike, EMNRD
Subject: Closure Approval - Marathon - Cypress 1H - (2RP-5480) 6-6-2019
Attachments: Closure Approval - Marathon - Cypress 1H - (2RP-5480) 8.14.19.pdf

Isaac,

We have received your closure report and final C-141 for **2RP-5480 Cypress 1H**, thank you. This closure is approved.

Please let me know if you have any further questions.

Regards,

Robert J Hamlet
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 840-5963
Robert.Hamlet@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Castro, Isaac (MRO) <icastro@marathonoil.com>
Sent: Monday, August 5, 2019 5:34 PM
To: Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Johnson, Misti M. (MRO) <mjohnson4@marathonoil.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Cc: Heather Patterson <heather.patterson@soudermiller.com>
Subject: RE: Marathon Oil Company - Final C141 & Closure Report - Cypress 1H

Good afternoon,

Please find attached the closure report for Cypress 1H. This report has also been submitted online through the OCD online platform. Receipt is attached for your reference.

Thank you,

Isaac Castro

Advanced Environmental Technician
Marathon Oil Company - Permian Asset
4111 S. Tidwell Road
Carlsbad, NM 88220
Cell: (575) 988-0561 Email: icastro@marathonoil.com



From: Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>
Sent: Thursday, June 13, 2019 9:59 AM
To: Karrigan, Callie N. (MRO) <cnkarrigan@marathonoil.com>; Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Cc: Castro, Isaac (MRO) <icastro@marathonoil.com>; Heather Patterson <heather.patterson@soudermiller.com>
Subject: [External] RE: Marathon Oil Company - Initial C141 - Cypress 1H

Beware of links/attachments.

RE: Marathon Oil Company - Initial C141 - Cypress 1H

All,
The OCD tracking number for this release event is **2RP-5480**.
Thank you,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Karrigan, Callie N. (MRO) <cnkarrigan@marathonoil.com>
Sent: Tuesday, June 11, 2019 2:15 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Cc: Castro, Isaac (MRO) <icastro@marathonoil.com>; Heather Patterson <heather.patterson@soudermiller.com>
Subject: [EXT] Marathon Oil Company - Initial C141 - Cypress 1H

Good afternoon,

Please see the attached initial C141.

Thank you,

Callie

From: Karrigan, Callie N. (MRO)

Sent: Friday, June 7, 2019 9:27 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; jim.griswold@state.nm.us

Cc: Castro, Isaac (MRO) <icastro@marathonoil.com>; Heather Patterson <heather.patterson@soudermiller.com>

Subject: Marathon Oil Company - 24 hour notification - Cypress 1H

Good morning,

Last night at 6:30 pm, a third party working near the Cypress 1H location reported a load line leak. Upon further investigation by the Operator, the water load out valve at the load out pot was left cracked. Approximately 103 bbls of produced water was released. Approximately 60 bbls of standing fluids were recovered via vac truck.

A C141 will be submitted shortly.

Thank you,

Callie Karrigan

HES Professional – Environmental

Office: 575-297-0956

Cell: 405-202-1028