Venegas, Victoria, EMNRD

Venegas, Victoria, EMNRD
Wednesday, November 13, 2019 4:23 PM
'Baker, Adrian'; Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD;
blm_nm_cfo_spill@blm.gov
Littrell, Kyle; Ruth, Amy; Foust, Bryan
RE: Containment Inspection - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker
Lake CVX JV RR #007H) spill date 9-15-19
(C-141 Final) Ross Ranch 33-25-30 CTB 30-015-40762_XTO 11.13.19.pdf

- Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19 2RP-5687

Mr. Littrell,

OCD has received your closure request and final C-141 for - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19, **2RP-5687**, thank you. This closure is approved. Regards,

Victoria Venegas EMNRD OCD-District II Artesia NM <u>Victoria.Venegas@state.nm.us</u>

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Baker, Adrian <Adrian_Baker@xtoenergy.com>
Sent: Tuesday, October 1, 2019 3:20 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>;
Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>
Cc: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>; Ruth, Amy <Amy_Ruth@xtoenergy.com>; Foust, Bryan
<Bryan_Foust@xtoenergy.com>
Subject: [EXT] RE: Containment Inspection - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR
#007H) spill date 9-15-19

Good afternoon,

Below is a 48-hour email notification for liner inspection at the Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19. We are unable to inspect the liner this week due to all of the recent rain in the area. The facility is located on a road that is currently underwater and impassible at this time. We are hoping to inspect the liner on Monday October 7, 2019.

Thank you

XTO Energy Inc. 6401 N. Holiday Hill Dr. Midland, Tx 79707 Mobile:(432)-236-3808 adrian_baker@xtoenergy.com

From: Baker, Adrian
Sent: Monday, September 30, 2019 11:11 AM
To: 'Mike Bratcher' <<u>mike.bratcher@state.nm.us</u>>; 'Rob Hamlet' <<u>robert.hamlet@state.nm.us</u>>; 'Venegas, Victoria, EMNRD' <<u>Victoria.Venegas@state.nm.us</u>>
Cc: Littrell, Kyle <<u>Kyle_Littrell@xtoenergy.com</u>>; Ruth, Amy <<u>Amy_Ruth@xtoenergy.com</u>>; Foust, Bryan
<<u>Bryan_Foust@xtoenergy.com</u>>
Subject: Containment Inspection - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19

Good morning,

This is sent as 48-hour notification that we are scheduled to inspect this lined tank battery containment on October 2, 2019 at 1100 pm MST. We will be submitting the Initial/Final C-141 on October 2, 2019.

GPS: 32.09301, -103.89244

Thank you Adrian Baker Safety, Health & Environmental Coordinator Permian Business Unit

XTO Energy Inc. 6401 N. Holiday Hill Dr. Midland, Tx 79707 Mobile:(432)-236-3808 adrian_baker@xtoenergy.com