

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Friday, January 10, 2020 8:24 AM
To: ggregson@marklshidlerinc.com; EMNRD-OCD-District1spills; Bratcher, Mike, EMNRD
Cc: Rose-Coss, Dylan H, EMNRD
Subject: RE: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135
Attachments: CFO_CAVE_KARST_PUBLIC_Updated_Cave_Potential.kmz

RE: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 – 32135

Mr. Gregson,

We cannot process your closure request because this report is incomplete. By Rule NMAC 19.15.29.12, for Remediation Plans and/or Closure Reports, the responsible party must submit a document that includes:

1. Scaled site map diagram with sample points clearly marked
2. Photographs of the remediated site prior to backfill
3. Site Assessment/Delineation summary (horizontal and vertical)
4. Delineation sample analytical results (lab tested)
5. Table containing analytical data
6. Description of proposed excavation depths corresponding to analytical table
7. Depth to groundwater evaluation, including fluid level data from New Mexico Office of the State Engineer or other documented evidence
8. Karst evaluation (see attachment)
9. FEMA National Flood map review
10. Signed and dated the corresponding part of form C-141 (Pages 3-5 for Remediation Plans or Page 6 for Closure Report)

If you need assistance, the current spill rule may be viewed here: <http://164.64.110.134/parts/title19/19.015.0029.html>

For further clarifications regarding the implementation of the spill rule, visit the OCD web site:
<http://www.emnrd.state.nm.us/OCD/documents/OCDInternalPolicy-SpillRuleClarifications.pdf>

Finally, all environmental correspondence for OCD-NM South, which currently encompasses OCD District 1 Hobbs and OCD District 2 Artesia, needs to go to the following email address: EMNRD-OCD-District1spills@state.nm.us

Regards,

*Victoria Venegas
EMNRD
OCD-District II*

Artesia NM
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Sent: Tuesday, January 7, 2020 12:01 PM
To: EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>
Subject: FW: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Dylan Rose-Coss

Petroleum Specialist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3477



From: Gregory B. Gregson <ggregson@marklshidlerinc.com>
Sent: Tuesday, January 7, 2020 11:11 AM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Subject: [EXT] FW: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Dear Mr. Rose-Coss:

Find attached various documents regarding the closure of C-141 Incident alpha-number NAB1912860106 for your review and further action.

Best Regards,

Gregory B. Gregson
Operations Manager



MARK L. SHIDLER, INC.

Mark L. Shidler, Inc. - Petroleum Exploration & Production
1313 Campbell Rd., Bldg. D
Houston, TX 77055
Direct: (713) 481-6487
Main: (713) 222-9291
Fax: (713) 224-5523

From: Gregory B. Gregson <ggregson@marklshidlerinc.com>
Sent: Tuesday, January 07, 2020 12:06 PM
To: Gregory B. Gregson <ggregson@marklshidlerinc.com>
Subject: RE: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Gentlemen:
Please find attached closure documentation for the above Re well.
Should your office require additional information, please contact the undersigned.

Best Regards,

Gregory B. Gregson
Operations Manager



MARK L. SHIDLER, INC.

Mark L. Shidler, Inc. - Petroleum Exploration & Production
1313 Campbell Rd., Bldg. D
Houston, TX 77055
Direct: (713) 481-6487
Main: (713) 222-9291
Fax: (713) 224-5523

From: Gregory B. Gregson
Sent: Friday, June 21, 2019 12:42 PM
To: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Subject: RE: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Dear Mr./Mrs. Rose-Coss:
Yesterday I contacted the dirt contractor (leaving a voice mail message) for a date to begin/initiate removal of the oil contaminated soils at the above Re production site. As of this writing, I have not received a reply/notice from them (Liberty Maintenance Service)

Best Regards,

Gregory B. Gregson
Operations Manager



MARK L. SHIDLER, INC.

Mark L. Shidler, Inc. - Petroleum Exploration & Production

1313 Campbell Rd., Bldg. D
Houston, TX 77055
Direct: (713) 481-6487
Main: (713) 222-9291
Fax: (713) 224-5523

From: Rose-Coss, Dylan H, EMNRD <DylanH.Rose-Coss@state.nm.us>
Sent: Friday, June 21, 2019 9:17 AM
To: Gregory B. Gregson <ggregson@marklshidlerinc.com>
Subject: RE: C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Hello Mr. Gregson,

I was curious to the status of the remediation of this release? I'm reviewing old emails trying to keep things from falling through the cracks and just want to make sure you are not waiting on me for anything?

Thanks,

Dylan Rose-Coss

Environmental Scientist
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505

(505) 476-3488

From: Gregory B. Gregson <ggregson@marklshidlerinc.com>
Sent: Monday, May 6, 2019 12:21 PM
To: EMNRD-OCD-District1spills <EMNRD-OCD-District1spills@state.nm.us>
Subject: [EXT] C-141 - State 23-1, M-23-T14S-R34E, Lea Co., NM - 30-025-20419 - 32135

Gentlemen:

Pursuant Mr. Kautz's request of this date, please find attached various documents regarding the crude oil release at the above Re well.

Best Regards,

Gregory B. Gregson
Operations Manager



MARK L. SHIDLER, INC.

Mark L. Shidler, Inc. - Petroleum Exploration & Production
1313 Campbell Rd., Bldg. D
Houston, TX 77055
Direct: (713) 481-6487
Main: (713) 222-9291
Fax: (713) 224-5523