

District I
4625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-26761.

Release Notification and Corrective Action

000004125 32110

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Co.	Contact Kenneth N. Andersen
Address 1004 Penbrook, Odessa, TX 79762	Telephone No. 505.676.5569
Facility Name Cabin Lake Water Injection Facility AKA James A Waterflood Station	Facility Type Oil and Water

Surface Owner State of New Mexico	Mineral Owner State of New Mexico	Lease No K3271
--	--	-----------------------

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 22S	Range 30E	Feet from the 1250	North/South Line S	Feet from the 1150	East/West Line E	County Eddy
-------------------------	---------------------	------------------------	---------------------	------------------------------	------------------------------	------------------------------	----------------------------	-----------------------

Latitude **32.41648N** Longitude **103.84721W**

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 11bbl (0 oil, 11 water)	Volume Recovered (0 oil, 10 water)
Source of Release 1/4"X3" nipple on discharge of west injection pump	Date and Hour of Occurrence 03/18/04 0320hrs	Date and Hour of Discovery 03/18/04 0430hrs
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	RECEIVED
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		MAR 22 2004

OGD-ARTESIA

Describe Cause of Problem and Remedial Action Taken.*

The 1/4"X3" nipple was broken clean off in the threads due to fatigue. Replaced nipple, needle valve, & bushing with schedule 80 (2000# WP) stainless steel.

Describe Area Affected and Cleanup Action Taken.*

5'X150' of a diked dry caliche facility pad with no cows present. The free fluid was picked up and the area was backed dragged with a back hoe. See attachment for further information.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Kenneth N. Andersen</i>	OIL CONSERVATION DIVISION	
Printed Name: Kenneth N Andersen	TIM W. GUM	
Title: SHEaR Specialist	Approved by District Supervisor DISTRICT 7 SUPERVISOR	
E-mail Address: ken.n.andersen@conocophillips.com	Approval Date: 5/4/2004	Expiration Date:
Date: 03/18/04 Phone: 505.676.5569	Conditions of Approval:	Attached <input type="checkbox"/>

- Attach Additional Sheets If Necessary