Submit 3 Copies To Appropriate District Office District I  State of New Mexico Energy, Minerals and Natural Resources	Form C-103 March 4, 2004
1625 N. French Dr., Hobbs, NM 88240	WELL API NO. 30-015-04048
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION  District III 1220 South St. Francis Dr.	5. Indicate Type of Lease STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	6. State Oil & Gas Lease No. B-8146
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)  1. Type of Well:	BURNHAM GB SA UNIT  8. Well Number
Oil Well Gas Well Other Water Injection	6-2
2. Name of Operator CBS OPERATING CORP. AUG 2 6 2004	9. OGRID Number 216 85 2
P O BOX 2236 MIDLAND TX 79702 OCD-ARTERIA	10. Pool name or Wildcat SQUARE LAKE GB SA
4. Well Location	
Unit Letter N : 660 feet from the South line and 1980 feet from the West line	
Section 2 Township 17S Range 30E NMPM Eddy County NM  11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
3745 GL  Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached)	
Pit Location: ULSectTwpRngPit typeDepth to GroundwaterDistance from nearest fresh water well	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng;	
feet from theline andfeet from theline	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
	EQUENT REPORT OF:
PERFORM REMEDIAL WORK  PLUG AND ABANDON  REMEDIAL WORK	☐ ALTERING CASING ☐
TEMPORARILY ABANDON	LING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING MULTIPLE CASING TEST AND COMPLETION CEMENT JOB	
OTHER: OTHER: Retu	rn to injection 🛛
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.	
8-19-04 MI&RU pump truck and chart recorder. Run MIT, pressured up to 475 psi for 30 minutes.	
Test witnessed by OCD representative, Gerry Gu	ye. (See attached chart)
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURE CO. A SUS DE TITLE ENGINEER	DATE8-25-04
Type or print name M. A. SIRGO, III E-mail address: mastres@aol.comgelephone No.	
(This space for State use)	
APPPROVED BY / SHELLY STITLE OF /	DATE 8-27-04
Conditions of approval, if any:	
<b>'</b>	

