District I 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210 District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

June 1, 2004

Form C-144

For drilling and production facilities, submit to appropriate NMOCD District Office.
For downstream facilities, submit to Santa Fe office

Pit or Below-Grade Tank Registration or Closure Is pit or below-grade tank covered by a "general plan"? Yes No		
Type of action: Registration of a pit or below-grade tank 🗵 Closure of a pit or below-grade tank 🗌		
Operator:DEVON ENERGY PRODUCTION CO., LPTelephone: _405 228-8209e-mail address:linda.guthrie@dvn.com		
Pit Type: Drilling Production Disposal EVISTING Workover Emergency Lined Unlined Liner type: Synthetic Thickness 12 mil Clay Pit Volumebbl	Below-grade tank Volume:bbl Type of fluid: Construction material: Double-walled, with leak detection? Yes If not, explain why not. RECEIVED	
Depth to ground water (vertical distance from bottom of pit to seasonal high water elevation of ground water.)	Less than 50 feet 50 feet or more, but less than 100 feet 100 feet or more	(20 points) (10 points)
Wellhead protection area: (Less than 200 feet from a private domestic water source, or less than 1000 feet from all other water sources.)	Yes No	(20 points)
Distance to surface water: (horizontal distance to all wetlands, playas, irrigation canals, ditches, and perennial and ephemeral watercourses.)	Less than 200 feet 200 feet or more, but less than 1000 feet 1000 feet or more	(20 points) (10 points)
	Ranking Score (Total Points)	
If this is a pit closure: (1) attach a diagram of the facility showing the pit's relationship to other equipment and tanks. (2) Indicate disposal/ocation: (check the onsite box if		
your are burying in place) onsite 🗌 offsite 🗍 If offsite, name of facility		
remediation start date and end date. (4) Groundwater encountered: No 🗌 Yes 🔲 If yes, show depth below ground surfaceft. and attach sample results. (5)		
Attach soil sample results and a diagram of sample locations and excavations.		
Additional Comments:		
Devon requests approval to use existing put at location instead		
Devon requests approval to use existing put at location instead of previously approved put at Righthand Campon 35 Federal # 3		
This pit was lined w/ a 12 mil liner + felt when built		
Cuttings to be put in fit @ 3544 which has 12 mil. Ling		
l hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that the above-described pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit , or an (attached) alternative OCD-approved plan . Date: 09/29/04		
Printed Name/Title_Linda Guthrie/ Regulatory SpecialistSignature		
Your certification and NMOCD approval of this application/closure does not relieve the operator of liability should the contents of the pit or tank contaminate ground water or otherwise endanger public health or the environment. Nor does it relieve the operator of its responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Approval: Printed Name/Title Juild Rep P Signature Dat DCT 1 2004		