

District I - (505) 393-6161
P.O. Box 1980
Hobbs, NM 88241-1980
District II - (505) 748-1283
1301 W. Grand Ave.
Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Road
Aztec, NM 87410
District IV - (505) 827-7131

State of New Mexico
Energy Mineral and Natural Resources Department
Oil Conservation Division
1220 South St. Francis Drive
Santa Fe, New Mexico 87505
(505) 476-3440

Form C-141
Originated 2/13/97

Submit 2 copies to
Appropriate District
Office in accordance
with Rule 116 on
back side of form

30-015-28621
NLRN 429229632

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name Marathon Oil Company	Contact Dwight Brodbeck
Address PO Box 1324, Artesia, NM 88211	Telephone No. 505-457-2621
Facility Name NIBU 21	Facility Type Production Battery

RECEIVED

OCT 06 2004

Surface Owner BLM	Mineral Owner BLM	Lease No. NM05609
-----------------------------	-----------------------------	-----------------------------

BLM ARTESIA

LOCATION OF RELEASE

Unit Letter F	Section 11	Township 21S	Range 23E	Feet from the 0	North/South Line 0	Feet from the 0	East/West Line 0	County Eddy
-------------------------	----------------------	------------------------	---------------------	---------------------------	------------------------------	---------------------------	----------------------------	-----------------------

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 59	Volume Recovered 58		
Source of Release Steel produced water tank	Date of Occurrence 09/30/04	Hour of Occurrence 2:00 AM	Date of Discovery 09/30/04	Hour of Discovery 7:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Van Barton			
By Whom? Dwight Brodbeck	Date of Notification 09/30/04	Hour of Notification 1:35 PM		
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)


Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary)

The water tank was evidently struck by lightning during a thunderstorm.

Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets if Necessary)

The release was contained inside of the lined dike surrounding the tanks. The produced water and rain water were picked up by vacuum truck and disposed of in our permitted disposal well. No further action is anticipated.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulation all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Dwight A. Brodbeck	Approved by District Supervisor:	Expiration Date:
Title: Production Supervisor	Approval Date:	Attached <input type="checkbox"/>
Date: 10/1/04	Conditions of Approval:	
Phone: (505) 457-2621		

F
I