District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

Form C-141 Revised October 10, 2003

OPERATOR ☑ Initial Report ☐ Final Report Name of Company CBS Operating Corp. Contact M.A.Sirgo,III Benito Sanchez Address POBox 2236, Midland,TX 79702 Telephone No. 432/685-0878 432/557-1577 Facility Name North Square Take Unit No. 160 Facility Type North Square Take Unit No. 160 Surface Owner USA Mineral Owner USA Lease No. NM081277
Address POBox 2236, Midland, TX 79702 Telephone No. 432/685-0878 432/557-1577 Facility Name North Square Lake Unit No. 160 Facility Type North Square Lake Unit No. 160
Address POBox 2236, Midland, TX 79702 Telephone No. 432/685-0878 432/557-1577 Facility Name North Square Lake Unit No. 160 Facility Type North Square Lake Unit No. 160
Surface Owner LISA Mineral Owner LISA Lease No. NM0.812.77
Datace Owner Coll
LOCATION OF RELEASE
Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County
N 31 16S 31E 330 south 1357.4 west Eddy
Latitude Longitude
NATURE OF RELEASE
Time of Palesca, W2+Or W/Oil Skim Waluma of Palesca 12 hold Waluma Pagayand
Source of Release Hole in casing at wellhead Date and Hour of Occurrence 1/12 Date and Hour of Discovery 11-12-04
was immediate Notice Given?
Yes No Not Required Paul Evans at BLM found leak
By Whom? Date and Hour
Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.
☐ Yes ☑ No RECEIVED
If a Watercourse was Impacted, Describe Fully.* DEC - 9 2004
SON
Describe Cause of Problem and Remedial Action Taken.*
Hole developed in casing below wellhead. An emergency pit was dug to contain fluid. This
pit was cleaned out and lined. During the next two weeks, the field became rain soaked
and equipment could not get in location. 60 bbls.mostly rain water was removed. Temp pit
Describe Area Affected and Cleanup Action Taken.* was closed 12/1/04.
The area affected was the well pad around the pumping unit.
Repair and clean up as per attached Sundry.
repair and cream up as per accached sundry.
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and
regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger
public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health
or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other
federal, state, or local laws and/or pegulations. OIL CONSERVATION DIVISION
Signature: Ch. 16 - Hugo
Printed Name: M. A. Sirgo, III Approved by District Supervisor:
Signature: M. A. Sirgo, III Approved by District Supervisor: Title: Engineer Approval Date: Expiration Date:
E-mail Address: mastres@aol.com Conditions of Approval:
Date: 12-7-04 Phd:32/685-0878
Attach Additional Sheets If Necessary

FORM APPROVED Form 3160-5 UNITED STATES OM B No. 1004-0137 Express March 31, 2007 DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT 5. Lease Serial No. NM081277 SUNDRY NOTICES AND REPORTS ON WELLS 6. If Indian, Allottee or Tribe Name Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7. If Unit or CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE- Other instructions on reverse side. NORTH SQUARE LAKE UNIT 1. Type of Well Oil Well Gas Well Other 8. Well Name and No. NORTH SQUARE LAKE UNIT 160 2 Name of Operating CORP. 9. API Well No. 3a Address P O BOX 2236 30-015-04953 3b. Phone No. (include area code) 10. Field and Pool, or Exploratory Area MIDLAND TX 79702 432/685-0878 SOUARE LAKE GB SA 4. Location of Well (Footoge, Sec., T., R., M., or Survey Description) 11. County or Parish, State EDDY 330' FSL & 1357.4' FWL UL N Sec. 31 T16S R31E 12. CHECK APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Water Sheet-Off Production (Start/Resume) Acidize Decrea Notice of Intent Well Integrity __ Alter Casing Fracture Treat Reclamation Mother Repair surf hole in Casing Repair New Construction Reconstate Subscorent Report casing and reclaim pad Change Plans Temporarily Abandon Plug and Abandon Final Abandonment Notice area affected Water Disposal Plug Back Convert to Enjection 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent seports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has determined that the site is ready for final inspection.) Set permitted 50 bbl fiberglass tank in ground to contain discharge from leak at wellhead. MI&RU pulling unit. Replace section of casing @ surface where hole is located. Haul all fluids from fiberglass tank to disposal. 4) Notify NMOCD & BLM Reps to begin sampling of prior emergency pit location and affected pad areas. All samples to be taken to Cardinal Labs in Hobbs to determine contamination depth. 5) Remove all contaminated soil and take to land farm. 6) Replace with clean soil. 7) Return well to production. Accepted for record - NMOCD 14. Thereby certify that the foregoing is true and correct Name (Printed/Typed) M. A Sirgo / IXI Title Engineer Signature O Date December 7, 2004 THIS SPACÉ FOR FEDERAL OR STATE OFFICE USE Date Title Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or section of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)