

## District I

1625 N. French Dr., Hobbs, NM 88240

## District II

1301 W. Grand Avenue, Artesia, NM 88210

## District III

1000 Rio Brazos Road, Aztec, NM 87410

## District IV

1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico

## Energy Minerals and Natural Resources

Form C-141

Revised June 10, 2003

## Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Submit 2 Copies to appropriate

District Office in accordance

with Rule 116 on back

side of form.

30-015-10376

## Release Notification and Corrective Action

## OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Merit Energy Corporation	Contact	Gene Brookshire
Address	P.O. Box 69	Telephone No.	505-420-5497
Facility Name	WB #29 4" Flowline	Facility Type	4" fiberglass flowline

Surface Owner	BLM	Mineral Owner	NA	Lease No.	LC-029426B
---------------	-----	---------------	----	-----------	------------

## LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from South Line	Feet from West Line	Longitude-W	Latitude-N	County
C	9	17S	31E	4920	1980			Eddy

## NATURE OF RELEASE

Type of Release	Volume of Release	Volume Recovered
Produced Water	40 bbl	0 bbl
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Broken 4" Fiberglass flowline	9/28/04 12:30 PM	9/28/04 12:30 PM
Was Immediate Notice Given?	If YES, To Whom?	
<input checked="" type="checkbox"/> YES <input type="checkbox"/> NO <input type="checkbox"/> Not Required	NMOCD and BLM	
By Whom?	Date and Hour	
Greg Leary - Merit Energy	9/29/04 11:00 AM	
Was a Watercourse Reached?	If YES, Volume Impacting the Watercourse	
<input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	NA	

If a Watercourse was Impacted, Describe Fully\*

Describe Cause of Problem and Remedial Action Taken. \*


Broken 4" fiberglass line. Repaired line - - area inaccessible to vacuum truck, thus no recovery attained.

Describe Area Affected and Cleanup Action Taken. \*

Approximate 2100-ft<sup>2</sup> area (30' X 70') ~300-ft north of WB#29 injection well. Area was roto-tilled and fertilized to augment hydrocarbon bio-degradation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:



Printed Name:

John Good

Title:

SESI - Project Consultant

E-Mail Address:

ballen@sesi-nm.com

Date:

1/6/2005

Phone:

505-397-0510

## OIL CONSERVATION DIVISION

T. Gurn by Mike Brantner  
Approved by District Supervisor:

Approval Date: 2/9/05

Expiration Date: N/A

Conditions of Approval: Area to be monitored for 12 month period for vegetation re-growth as recommended by SESI

☐ Attached