

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003


Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

NMLB/121358700

OPERATOR

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amber Cannon
Address 105 S. 4 TH Street	API Number 30-015-35217	Telephone No. 575-748-1471
Facility Name Jester SWD #4	Facility Type SWD	



Surface Owner Federal	Mineral Owner Federal	Lease No. NM-105213
--------------------------	--------------------------	------------------------

LOCATION OF RELEASE

Unit Letter C	Section 12	Township 24S	Range 29E	Feet from the 990'	North/South Line North	Feet from the 1650'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.23657 Longitude 103.94079

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 B/PW	Volume Recovered 30 B/PW
Source of Release Water Tank	Date and Hour of Occurrence 6/24/2011; AM	Date and Hour of Discovery 6/24/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/24/2011, PM (voicemail); 6/28/2011, AM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A flapper in the motor valve failed to completely shut and let water continue coming into the battery. The pump couldn't keep up and the tanks overflowed.

Describe Area Affected and Cleanup Action Taken.*
An approximate area of 60' X 10' (all released water was contained in lined/bermed battery). A valve upstream of the Jester SWD was shut and a vacuum truck was called to remove discharged water. All produced water was recovered from the lined/bermed battery. **Depth to Ground Water: <50' (approximately 18', Section 16, T24S-R29E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 20. Based on battery being lined/bermed and all water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Amber Cannon</i>	OIL CONSERVATION DIVISION	
Printed Name: Amber Cannon	Signed By <i>Mike Bratcher</i> Approved by District Supervisor.	
Title: Environmental Regulatory Agent Trainee	Approval Date: 8/1/2011	Expiration Date: NA
E-mail Address: acannon@yatespetroleum.com	Conditions of Approval: NA 2RP-807	Attached <input type="checkbox"/>
Date: Tuesday, July 05, 2011	Phone: 575-748-4111	

* Attach Additional Sheets If Necessary

2RP-807