District I 1625 N. French Dr., Hobbs, NM 88240 District II 1301 W. Grand Avenue, Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Ea NIM 97505

Form C-141 Revised October 10, 2003

Submit 2 Copies to appropriate District Office in accordance with Rule 116 on back side of form

MIR 1116757426			ativi	i and Co	orrective A	Ction													
MLB 1116757436				OPERATOR Initial Report Final Report															
Name of Company Devon Energy 6/37 Address 6488 Seven Rivers Hwy – P.O. Box 250				Contact Roy White, Foreman Telephone No. 575- 748-5234 Facility Type Lease No.															
												LOCA	TIO	N OF REI	LEASE				
										Unit Letter Section Townsh 14 24S		Range Feet from the 29E 1780'		South Line	Feet from the	East/West Line FEL		County Eddy	
										14 243	29E	1700			860'	PEL.		Zudy	
		Latitude – <u>N32</u>	2.2151	<u>6</u> * Longitu	de – <u>103.9492</u>	<u>7</u>													
		NAT	URE	OF RELI	EASE														
Type of Release				Volume of Release			Volume Recovered												
Produced Water				100 bbls			0												
Source of Release Above Ground Poly Line was ran over				Date and Hour of Occurrence 05/11/11 - 10:00 pm			Date and Hour of Discovery 05-11-11 – 10:00 pm												
Was Immediate Notice Given? ☐ Yes ☐ No ☐ Not Required				If VFS To Whom?															
/	Yes L	No L Not Re	quired	Jim Amo															
By Whom? Roy White, Foremen				Date and Hour 05-12-11 – 9:10 am															
Was a Watercourse Reached?				Date and Hour 05-12-11 – 9:10 am If YES, Volume Impacting the Watercourse. Sing damage to the line releasing 100 bbl of produced water															
	☐ Yes 🏻							KU.	16 × 265										
If a Watercourse was Impacted, Do	escribe Fully.*	•						k. 1/2	, Obj.										
Describe Cause of Problem and Re A truck had driven over an	above gro	und ploy line	causi	ng damag	e to the line re	eleasing													
onto the road with 0 bbl re that line and isolated the l																			
Describe Area Affected and Cleane Shut off all transfer pumps			olated	I the leak.	•														
hereby certify that the information regulations all operators are require	n given above	is true and comple	ete to th	e best of my	knowledge and ur	nderstand	that pursues for rele	ant to NMC	OCD rules and										
public health or the environment.	The acceptanc	e of a C-141 repor	rt by the	NMOCD ma	arked as "Final Re	port" does	s not relie	eve the opera	ator of liability										
should their operations have failed																			
or the environment. In addition, Nederal, state, or local laws and/or r		iance of a C-141 fo	eport at	es not reneve	e the operator of re	esponsion	ity for co	impitance wi	iin any other										
Signature: Mykol Horner				OIL CONSERVATION DIVISION Approved by District Supervised by Branches															
										Printed Name: Mykol Horne	r		'	ipproved by	Signed By 2	11/4	Benn	ulcon_	-
				Approval Date	: 6/16/201	/ Evr	iration E	Note:											
Field Tech 1	<u> </u>			pprovai Dall	. 4/16/201	, EXL	mation L	raic.											
E-mail Address: mykol.horne	r@dvn.con	1	_	Conditions of				Attached	П										
				Remediation	on per OCD Ru	les &		Allaciicu	_										
	PME 710 0	400			-			İ											
Date: Phone:	: 575-748-0	160	Guid	delines. SU	BMIT REMEDIA	ATION													
	essary		Guid	delines. SU	-	ATION		2RP	1-798										