

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-30251

Release Notification and Corrective Action

NMUB 1118835601

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Apache Corporation	873	Contact Natalie Gladden
Address PO Box 1849 Eunice NM 88231		Telephone No. 575-390-4186
Facility Name Randy Federal Transfer Station (nearest well Randy Federal #4)		Facility Type Water Station

Surface Owner BLM	Mineral Owner State	Lease No. 30-015-30251
-------------------	---------------------	------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	22	17S	30E	1650'	FNL	330'	FEL	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 180	Volume Recovered 160
Source of Release 2x1 swedge	Date and Hour of Occurrence 06/28/11	Date and Hour of Discovery 06/28/11 7am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade and Mike Bratcher; as well as Justin with BLM	
By Whom? Natalie Gladden	Date and Hour 942am 06/28/11	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

2x1 swedge on transfer pump busted releasing 180bbls of produced water and recovering 160bbls of produced water. The fluid was released both inside the bermed area as well as on the well pad for the Randy Federal #4. The swedge was replaced immediately.

Describe Area Affected and Cleanup Action Taken.*

Inside the berm and on the location pad will be remediated according to the NMOCD Guidelines to closure. There is no water wells with in a six mile radius. We have data that 2 miles west of this facility that we do not have water as well; refer to the Red Water Station release

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <u>Natalie Gladden</u>	OIL CONSERVATION DIVISION	
Printed Name: Natalie Gladden	Signed By: <u>Mike Bratcher</u> Approved by District Supervisor.	
Title: EHS Environmental Tech	Approval Date: <u>7/7/2011</u>	Expiration Date:
E-mail Address: <u>natalie.gladden@apachecorp.com</u>	Conditions of Approval: Remediation per OCD Rules & Guidelines. SUBMIT REMEDIATION PROPOSAL NOT LATER THAN: <u>8/7/2011</u>	Attached <input type="checkbox"/>
Date: 06/28/11 Phone: 575-390-4186		

* Attach Additional Sheets If Necessary

LRP-801