


District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Bravo Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505



Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-015-33410
NMLB 1113026590

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company OXY USA	Contact Kelton Beard
Address 1502 W Commerce Carlsbad, NM 88220	Telephone No. (O) 575 628 4100
Facility Name Cimarron 23 Fed #1	Facility Type Oil Well with Battery
Surface Owner BLM	Mineral Owner
Lease No. NM-11038 API# 30-015-33410	


LOCATION OF RELEASE

Unit Letter O	Section 23	Township 26S	Range 29E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release OIL	Volume of Release 16bbbls	Volume Recovered 5bbbls
Source of Release Valve	Date and Hour of Occurrence	Date and Hour of Discovery 25 April 1030hrs
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required	If YES, To Whom? N/A	
By Whom?	Date and Hour See Above	
Was a Watercourse Reached? ☐ Yes ☒ No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A valve was kicked open by a cow. All released liquid remained inside the walls of the battery. A vac truck was summoned to remove all free standing liquid		
Describe Area Affected and Cleanup Action Taken.* The affected area was contained to the inside of the fire walls. Depth to groundwater is 100'. Chloride field test were first taken to determine the presence of chlorides. Based upon field test results, four feet of contaminated material was removed from inside the battery. Five sample points were then selected for sampling and lab analysis for chlorides, TPH, and BTEX. (See attached lab results.) These results were then presented to NM OCD and BLM seeking permission for closure. Both parties granted closure permission. The excavated area was then back filled with clean material with the fire walls being re-built and a fence installed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD (marked as "Final Report") does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kelton Beard	Approved by District 	
File: HFS - specialist	Approval Date: AUG 09 2011	Expiration Date: NA
Mail Address: Kelton Beard, 1502 W Commerce, Carlsbad, NM 88220	Conditions of Approval: NA	Attached ☐
Date: 11 June 11 Phone: 575 628 4100		

* Attach Additional Sheets If Necessary

2AP-777