

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JUN 17 2011

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

nmcb 11222 50190

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Amanda Trujillo
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Dagger Draw Gas Gathering System (Hinkle Line)	API Number	Facility Type Pipeline
		Order Number 2RP- 823

Surface Owner Fee	Mineral Owner Fee	Lease No.
----------------------	----------------------	-----------

Ndbup 115 (30-015-28033) FOR DATA ENTRY

LOCATION OF RELEASE

Unit Letter A	Section 28	Township 19S	Range 25E	Feet from the 990	North/South Line North	Feet from the 600	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

NATURE OF RELEASE

Type of Release Gas	Volume of Release 500 MCF Gas	Volume Recovered 0
Source of Release Weld on 8" poly gas line broke	Date and Hour of Occurrence 06/01/2011	Date and Hour of Discovery 06/01/2011- PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD/Artesia	
By Whom? Amanda Trujillo - Yates Petroleum Corporation	Date and Hour 06/01/2011 pm called OCD Office. Email followed on 06/02/2011	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A



Describe Cause of Problem and Remedial Action Taken.*

A weld broke on and 8" poly line, causing a gas leak. Valves were shut off to stop leak and make necessary repairs. Leak occurred with in valve box.

Describe Area Affected and Cleanup Action Taken.*

Leak occurred within a valve box. The impacted area is located around and within the valve box. Vertical and horizontal delineation samples will be taken and analysis ran for TPH and BTEX once all contaminated material has been removed. Depth to Ground Water: >100' (approx. 150', per New Mexico Chevron/Texaco Trend Map); Wellhead Protection Area: No; Distance to Surface Water Body: >1000'; SITE RANKING IS 20.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By  Approved by District Supervisor:	
Title: Environmental Scientist	Approval Date: AUG 10 2011	Expiration Date:
E-mail Address: atrujillo@yatespetroleum.com	Conditions of Approval:	Attached <input type="checkbox"/>

Date: Friday, June 17, 2011 Phone: 575-748-4310

Attach Additional Sheets If Necessary

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

9/10/2011

2RP-823