

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmLB1122336083

OPERATOR

☒ Initial Report ☐ Final Report

| | | |
|---|--------|--------------------------------|
| Name of Company OXY USA | 192463 | Contact Kelton Beaird |
| Address 1502 W. Commerce Carlsbad, NM 88220 | | Telephone No. (O) 575-628-4100 |
| Facility Name Mckittrick 11-5 | | Facility Type SWD |

| | | |
|---------------|---------------|---------------------------|
| Surface Owner | Mineral Owner | Lease No. API: 3001533611 |
|---------------|---------------|---------------------------|

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| L | 11 | 22S | 24E | | | | | Eddy |

Latitude _____ Longitude _____

NATURE OF RELEASE

| | | |
|--|---|---|
| Type of Release Produced Water | Volume of Release 85 | Volume Recovered 80 |
| Source of Release Injection Pump | Date and Hour of Occurrence | Date and Hour of Discovery 7-5-11 @ 10:00am |
| Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? Mike Bratcher: NMOCD | |
| By Whom? Kelton Beaird (Oxy) | Date and Hour See above 7/5/11 4:55 P | |
| Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | |

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Injection pump cracked and leaked. Vacuum Truck was called to pick up standing fluid

Describe Area Affected and Cleanup Action Taken.*

Area affected was inside the terms. Area will be sampled and cleaned up per NMOCD and BLM guidelines

RECEIVED

JUL 11 2011

NMOCD ARTESIA

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:

Printed Name: Kelton Beaird

Title: HES Specialist

E-mail Address: kelton_beaird@oxy.com

Date: 7-6-11

OIL CONSERVATION DIVISION

Signed By

Approved by District Supervisor:

Approval Date:

AUG 11 2011

Expiration Date:

Conditions of Approval:

Attached ☐

Remediation per OCD Rules &
Guidelines. SUBMIT REMEDIATION
PROPOSAL NOT LATER THAN:

9/11/2011

JRB-827

* Attach Additional Sheets If Necessary