

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nmlb1122742820

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	OGRID Number 25575	Contact Robert Asher
Address 104 S. 4 TH Street	Telephone No. 575-748-1471	
Facility Name Rudolph ATX State Com. #3-H	API Number 30-015-37997	Facility Type Battery

Surface Owner State	Mineral Owner State	Lease No. V-4567
------------------------	------------------------	---------------------


LOCATION OF RELEASE

Unit Letter M	Section 16	Township 19S	Range 31E	Feet from the 330'	North/South Line South	Feet from the 660'	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.65389 Longitude 103.88026

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 75 B/PW	Volume Recovered 75 B/PW
Source of Release Water tank	Date and Hour of Occurrence 7/21/2011; AM	Date and Hour of Discovery 7/21/2011; AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/NMOCD II	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 7/21/2011, AM (email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

Water hauler did not pick up load of water before it overflowed out of tank.. The well was shut in, vacuum truck was called to the location.

Describe Area Affected and Cleanup Action Taken.*

An approximate area of 100' X 5' (all released water was contained in lined/bermed battery). All produced water was recovered. **Depth to Ground Water: >100' (approximately 130', Section 36, T19S-R31E, per NMOSE), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Based on battery being lined/bermed and all water recovered, Yates Petroleum Corporation requests closure.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Robert Asher	Signed By <u><i>Mike Bratcher</i></u> Approved by District Supervisor:	
Title: Environmental Regulatory Agent	Approval Date: <u>AUG 15 2011</u>	Expiration Date: <u>NA</u>
E-mail Address: boba@yatespetroleum.com	Conditions of Approval: <u>NA</u> <u>2RP-847</u> <i>Final</i>	Attached <input type="checkbox"/>
Date: Friday, July 22, 2011 Phone: 575-748-4217		

* Attach Additional Sheets If Necessary

2RP-847