

Bratcher, Mike, EMNRD

From: LeBlanc, Christopher S <ChristopherLeBlanc@chevron.com>
Sent: Friday, April 21, 2017 8:18 AM
To: Bratcher, Mike, EMNRD; Amos, James
Subject: Henshaw Deep Unit 5 Battery Reclamation
Attachments: Lab Analysis 2-27-17.pdf; Lab Summary 2-27-17.pdf

Gentlemen,

We are currently planning the reclamation of the Henshaw Deep Unit 5 Battery in Eddy County, NM.

There was a recent small spill (20' x 50' oil) at this location several months ago. From what I understand the spill volume was calculated to be less than 5 bbl. I've had samples collected (2 within the leak area and 4 that surround the leak area to find the horizontal edges).

I have attached the analyticals and lab summary for your review. My current plan is to remove ~18" of the contaminated soil within the spill area (below in red) and fill with native top soil to establish a growing medium.

Please let me know if this is acceptable. If you like, we can meet on location to review the area in more detail.



Thanks,

Chris S. LeBlanc

Facilities Engineer

Chevron North America Exploration & Production Company

Mid-Continent Business Unit

6301 Deauville Ave, Room N2205

Midland, TX 79707

Tel 432 687 7894

Cell 337 356 9538

ChristopherLeBlanc@chevron.com

Please provide CSOC feedback at <http://csocbehavior.chevron.com/>