

District I  
 1625 N. French Dr., Hobbs, NM 88240  
 District II  
 811 S. First St., Artesia, NM 88210  
 District III  
 1000 Rio Brazos Road, Aztec, NM 87410  
 District IV  
 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
 Energy Minerals and Natural Resources  
 Oil Conservation Division  
 1220 South St. Francis Dr.  
 Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nABI626654019

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Wade Dittrich
Address	PO Box 4294; Houston, TX 77210	Telephone No.	(575) 390-2828
Facility Name	Federal 29 #008 CTB	Facility Type	Battery

Surface Owner	BLM	Mineral Owner		API No.	30-015-27266
---------------	-----	---------------	--	---------	--------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	29	23S	31E					Eddy County, NM

Latitude N 32.26896° Longitude W -103.80605° NAD83

**NATURE OF RELEASE**

Type of Release	Oil and produced water	Volume of Release	1.5 bbls oil, 3.5 bbls produced water	Volume Recovered	4 bbls
Source of Release	Excessive water caused the tank to spill over	Date and Hour of Occurrence	09/07/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson-NMOCD; Shelly Tucker-BLM		
By Whom?	Kathy Purvis, BBC International, Inc.	Date and Hour	09/07/2016 @ 3:24 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
 n/a

Describe Cause of Problem and Remedial Action Taken.\*  
 Excessive water caused the tank to spill 1.5 bbls of oil and 3.5 bbls of produced water. A vacuum truck recover 4 bbls of fluids.

Describe Area Affected and Cleanup Action Taken.\*  
 The affected area is approximately 15' x 30' on location inside lined containment. Remediation was completed by removing the impacted material from within the lined containment and replacing it with clean material.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Wade Dittrich	Approved by Environmental Specialist 	
Title: Environmental Specialist	Approval Date: 7/23/2018	Expiration Date: N/A
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval: Like approval BLM	Attached <input type="checkbox"/>
Date: 7-10-18	Phone: (575) 390-2828	<b>FINAL</b>

\* Attach Additional Sheets If Necessary