

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	OXY USA INC OGRID:16696	Contact	WADE DITTRICH
Address	1017 W. STANOLIND HOBBS NM 88240	Telephone No.	575-390-2828
Facility Name	CEDAR CANYON 22 Central Satellite	Facility Type	BATTERY
Surface Owner	FEDERAL	Mineral Owner	FEDERAL
		API No.	30-015-40668

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	22	24S	29E					EDDY

Latitude\_32.20137\_ Longitude\_-103.97434 \_ NAD83

### NATURE OF RELEASE

Type of Release	Oil and Produced Water	Volume of Release	20 bbls oil 80 bbls Produced Water	Volume Recovered	10 bbls recovered- all inside containment
Source of Release	Dump Valve on Oil Tank	Date and Hour of Occurrence	07-31-2018	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	MARIA PRUETT-NMOCD; MIKE BRATCHER-NMOCD; SHELLY TUCKER-BLM		
By Whom?	WADE DITTRICH	Date and Hour	7-31-2018		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

Leak was caused by a failure on oil tank dump valve

Describe Area Affected and Cleanup Action Taken.\*

The impacted area is 50 x 30 ft. Leak is inside containment area (measurements are subject to change with GPS tracking). Leak is inside lined containment area. Remediation will be completed in accordance with a remediation plan approved by the NMOCD and BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: WADE DITTRICH	Approved by Environmental Specialist: Maria Pruett		
Title: ENVIRONMENTAL COORDINATOR	Approval Date: 08/16/18	Expiration Date: N/A	
E-mail Address: wade_dittrich@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 08/13/2018	Phone: 575-390-2828	N/A	2RP-4920

\* Attach Additional Sheets If Necessary

A#:pMAP1822868720

I#:nMAP1822868861