District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 OCD Rec'd:08/10/18

Form C-141 Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

2RP-5024

Santa Fe, NM 8/303												
Release Notification and Corrective Action												
						OPERATOR				al Report		Final Report
Name of Company: EOG Resources, Inc						Contact: Jamon Hohensee						*
Address: 5509 Champions Dr, Midland TX, 7976						Telephone No.: 432-556-8074						
Facility Name: Stella Blue 30 Fed Com 701						Facility Type: Well						
Surface Owner: BLM Mineral Owne						:: BLM			API No. 30015449200000			
LOCATION OF RELEASE												
Unit Letter	Letter Section Township Range Feet from the No				Nort	th/South Line Feet from the East			t/West Line County			
Latitude 32.0081 Longitude -103.8244												
NATURE OF RELEASE												
Type of Rele	ase: Water	based drilling	11113		Release: 120bbls	s	Volume Recovered: 30 bbls					
Source of Release: water tanks						Date and Hour of Occurrence			Date and Hour of Discovery			
						7/31/18			7/31/18			
Was Immediate Notice Given?												
	oourgo Dago	shad?		Date and Hour If YES, Volume Impacting the Watercourse.								
Was a Watercourse Reached? ☐ Yes ☒ No ☐ If YES, Volume Impacting the Watercourse.												
If a Watercourse was Impacted, Describe Fully.*												
na												
Describe Cause of Problem and Remedial Action Taken.*												
						241 * 1 111 4	1 6 1	.1	1.0	11		120111
On //31/18 1	Was discov	ered that wat	er drilling	mud was flowing area to the Sou	out of	The valve we	anks from a valve	e that was	s left parti	ally open. A	pprox .	120bbls of
mulus were re	sicascu oiiu	o uie pad and i	Surroundn	ig area to the Sou	mwesi.	. The valve was	s closed and 3000	ois were r	ecovered t	by vac truck	•	į
Describe Are	a Affected	and Cleanup /	Action Tal	cen.*	_						***********	
				itory standards. C	ontami	inated soils wil	l be transferred to	o an appre	oved dispo	sal facility.	Site wi	ll be brought
back to natur	al state with	appropriate	seed mixes	s for the area.				11	1	•		J
T1 1	0 1 11		1									
	•	_		is true and comp		•	_					
				nd/or file certain r ce of a C-141 repo								
should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,					p		o the operator of	· • • • • • • • • • • • • • • • • • • •	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	, , , , , , , , , , , , , , , , , , ,		ou.c.
0IL CONSERVATION DIVISION												
	7 7	// /_						~		22,122		
Signature:	>m/	1) /		11111								
Drintad Man	y Ioman II.	hanaac		Approved by Environmental Specialist:								
Printed Name	5. Jamon HC	mensee		-								
Title: Environmental Representative						Approval Date: 10/24/18			Expiration Date: N/A			
E mail Address iamon habansas (Casaras areas acres						Conditions of Appropriate						
E-mail Address: jamon_hohensee@eogresources.com						Conditions of Approval:				Attached		

* Attach Additional Sheets If Necessary

Phone: 432-556-8074

A#: pMAP1829767425 I#: NMAP1829767907